

AD-A104 620

CONSOER TOWNSEND AND ASSOCIATES LTD ST LOUIS MO
NATIONAL DAM SAFETY PROGRAM, LOST LAKE DAM (M010212), MISSISSIP--ETC(U)
SEP 79 W 6 SHIPRIN


F/O 13/13

DACW43-79-C-0075

ML

UNCLASSIFIED

100
A
DOWNSIDE



LEVEL II

①

MISSISSIPPI-SALT-QUINCY RIVER BASIN

LOST LAKE DAM
LINCOLN COUNTY, MISSOURI
MO. 10212

**DTIC
ELECTE
SEP 28 1981
S D E**

AD A104620

**PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM**

THIS REPORT IS THE PROPERTY OF THE ARMY. IT IS TO BE CONTAINED A
NUMBER OF PAGES WHICH DO NOT
EXCEED 12 PAGES.



**United States Army
Corps of Engineers**

...Serving the Army
...Serving the Nation

St. Louis District

81 9 28 114

PREPARED BY: U. S. ARMY ENGINEER DISTRICT, ST. LOUIS

FOR: STATE OF MISSOURI

This document has been approved
for public release and sale; its
distribution is unlimited.

SEPTEMBER 1979

DTIC FILE COPY

DISCLAIMER NOTICE


**THIS DOCUMENT IS BEST QUALITY
PRACTICABLE. THE COPY FURNISHED
TO DTIC CONTAINED A SIGNIFICANT
NUMBER OF PAGES WHICH DO NOT
REPRODUCE LEGIBLY.**

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE		READ INSTRUCTIONS BEFORE COMPLETING FORM
1. REPORT NUMBER	2. GOVT ACCESSION NO. <i>AD-A104</i>	3. RECIPIENT'S CATALOG NUMBER <i>620</i>
4. TITLE (and Subtitle) Phase I Dam Inspection Report National Dam Safety Program Lost Lake Dam (MO 10212) Lincoln County, Missouri		5. TYPE OF REPORT & PERIOD COVERED Final Report
7. AUTHOR(s) Consoer, Townsend and Associates, Ltd.		6. PERFORMING ORG. REPORT NUMBER
9. PERFORMING ORGANIZATION NAME AND ADDRESS U.S. Army Engineer District, St. Louis Dam Inventory and Inspection Section, LMSED-PD 210 Tucker Blvd., North, St. Louis, Mo. 63101		8. CONTRACT OR GRANT NUMBER(s) DACW43-79-C-0075✓
11. CONTROLLING OFFICE NAME AND ADDRESS U.S. Army Engineer District, St. Louis Dam Inventory and Inspection Section, LMSED-PD 210 Tucker Blvd., North, St. Louis, Mo. 63101		10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS
14. MONITORING AGENCY NAME & ADDRESS (if different from Controlling Office)		12. REPORT DATE September 1979
		13. NUMBER OF PAGES Approximately 90
		15. SECURITY CLASS. (of this report) UNCLASSIFIED
		15a. DECLASSIFICATION/DOWNGRADING SCHEDULE
16. DISTRIBUTION STATEMENT (of this Report) Approved for release; distribution unlimited.		
17. DISTRIBUTION STATEMENT (of the abstract entered in Block 20, if different from Report)		
18. SUPPLEMENTARY NOTES		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number) Dam Safety, Lake, Dam Inspection, Private Dams		
20. ABSTRACT (Continue on reverse side if necessary and identify by block number) This report was prepared under the National Program of Inspection of Non-Federal Dams. This report assesses the general condition of the dam with respect to safety, based on available data and on visual inspection, to determine if the dam poses hazards to human life or property.		

SECURITY CLASSIFICATION OF THIS PAGE(When Data Entered)



SECURITY CLASSIFICATION OF THIS PAGE(When Data Entered)

INSTRUCTIONS FOR PREPARATION OF REPORT DOCUMENTATION PAGE

RESPONSIBILITY. The controlling DoD office will be responsible for completion of the Report Documentation Page, DD Form 1473, in all technical reports prepared by or for DoD organizations.

CLASSIFICATION. Since this Report Documentation Page, DD Form 1473, is used in preparing announcements, bibliographies, and data banks, it should be unclassified if possible. If a classification is required, identify the classified items on the page by the appropriate symbol.

COMPLETION GUIDE

General. Make Blocks 1, 4, 5, 6, 7, 11, 13, 15, and 16 agree with the corresponding information on the report cover. Leave Blocks 2 and 3 blank.

Block 1. Report Number. Enter the unique alphanumeric report number shown on the cover.

Block 2. Government Accession No. Leave Blank. This space is for use by the Defense Documentation Center.

Block 3. Recipient's Catalog Number. Leave blank. This space is for the use of the report recipient to assist in future retrieval of the document.

Block 4. Title and Subtitle. Enter the title in all capital letters exactly as it appears on the publication. Titles should be unclassified whenever possible. Write out the English equivalent for Greek letters and mathematical symbols in the title (see "Abstracting Scientific and Technical Reports of Defense-sponsored RDT/E," AD-667 000). If the report has a subtitle, this subtitle should follow the main title, be separated by a comma or semicolon if appropriate, and be initially capitalized. If a publication has a title in a foreign language, translate the title into English and follow the English translation with the title in the original language. Make every effort to simplify the title before publication.

Block 5. Type of Report and Period Covered. Indicate here whether report is interim, final, etc., and, if applicable, inclusive dates of period covered, such as the life of a contract covered in a final contractor report.

Block 6. Performing Organization Report Number. Only numbers other than the official report number shown in Block 1, such as series numbers for in-house reports or a contractor/grantee number assigned by him, will be placed in this space. If no such numbers are used, leave this space blank.

Block 7. Author(s). Include corresponding information from the report cover. Give the name(s) of the author(s) in conventional order (for example, John R. Doe or, if author prefers, J. Robert Doe). In addition, list the affiliation of an author if it differs from that of the performing organization.

Block 8. Contract or Grant Number(s). For a contractor or grantee report, enter the complete contract or grant number(s) under which the work reported was accomplished. Leave blank in in-house reports.

Block 9. Performing Organization Name and Address. For in-house reports enter the name and address, including office symbol, of the performing activity. For contractor or grantee reports enter the name and address of the contractor or grantee who prepared the report and identify the appropriate corporate division, school, laboratory, etc., of the author. List city, state, and ZIP Code.

Block 10. Program Element, Project, Task Area, and Work Unit Numbers. Enter here the number code from the applicable Department of Defense form, such as the DD Form 1498, "Research and Technology Work Unit Summary" or the DD Form 1634, "Research and Development Planning Summary," which identifies the program element, project, task area, and work unit or equivalent under which the work was authorized.

Block 11. Controlling Office Name and Address. Enter the full, official name and address, including office symbol, of the controlling office. (Equates to funding/sponsoring agency. For definition see DoD Directive 5200.20, "Distribution Statements on Technical Documents.")

Block 12. Report Date. Enter here the day, month, and year or month and year as shown on the cover.

Block 13. Number of Pages. Enter the total number of pages.

Block 14. Monitoring Agency Name and Address (if different from Controlling Office). For use when the controlling or funding office does not directly administer a project, contract, or grant, but delegates the administrative responsibility to another organization.

Blocks 15 & 15a. Security Classification of the Report: Declassification/Downgrading Schedule of the Report. Enter in 15 the highest classification of the report. If appropriate, enter in 15a the declassification/downgrading schedule of the report, using the abbreviations for declassification/downgrading schedules listed in paragraph 4-207 of DoD 5200.1-R.

Block 16. Distribution Statement of the Report. Insert here the applicable distribution statement of the report from DoD Directive 5200.20, "Distribution Statements on Technical Documents."

Block 17. Distribution Statement (of the abstract entered in Block 20, if different from the distribution statement of the report). Insert here the applicable distribution statement of the abstract from DoD Directive 5200.20, "Distribution Statements on Technical Documents."

Block 18. Supplementary Notes. Enter information not included elsewhere but useful, such as: Prepared in cooperation with . . . Translation of (or by) . . . Presented at conference of . . . To be published in . . .

Block 19. Key Words. Select terms or short phrases that identify the principal subjects covered in the report, and are sufficiently specific and precise to be used as index entries for cataloging, conforming to standard terminology. The DoD "Thesaurus of Engineering and Scientific Terms" (TEST), AD-672 000, can be helpful.

Block 20. Abstract. The abstract should be a brief (not to exceed 200 words) factual summary of the most significant information contained in the report. If possible, the abstract of a classified report should be unclassified and the abstract to an unclassified report should consist of publicly-releasable information. If the report contains a significant bibliography or literature survey, mention it here. For information on preparing abstracts see "Abstracting Scientific and Technical Reports of Defense-Sponsored RDT&E," AD-667 000.



DEPARTMENT OF THE ARMY
ST. LOUIS DISTRICT, CORPS OF ENGINEERS
210 NORTH 12TH STREET
ST. LOUIS, MISSOURI 63101

IN REPLY REFER TO

SUBJECT: Lost Lake Dam (Mo. 10212) Phase I Inspection Report

This report presents the results of field inspection and evaluation of the Lost Lake Dam (Mo. 10212).

It was prepared under the National Program of Inspection of Non-Federal Dams.

SUBMITTED BY: SIGNED
Chief, Engineering Division

28 SEP 1979

Date

APPROVED BY: SIGNED
Colonel, CE, District Engineer

27 SEP 1979
Date

Accession For	
NTIS GRA&I	<input checked="checked" type="checkbox"/>
DTIC TAB	<input type="checkbox"/>
Unannounced	<input type="checkbox"/>
Justification	
By _____	
Distribution/	
Availability Codes	
Dist	Avail and/or Special
A	33

LOST LAKE DAM

LINCOLN COUNTY, MISSOURI

MISSOURI INVENTORY NO. 10212

PHASE I INSPECTION REPORT

6 NATIONAL DAM SAFETY PROGRAM

Lost Lake Dam (~~Inventory Number~~) (MO 10212).
Mississippi-Salt-Quincy River Basin,
Lincoln County, Missouri.
Phase I Inspection Report.

PREPARED BY

CONSOER, TOWNSEND AND ASSOCIATES LTD.

ST. LOUIS, MISSOURI

AND

ENGINEERING CONSULTANTS, INC.

ENGLEWOOD, COLORADO

A JOINT VENTURE

UNDER DIRECTION OF

ST. LOUIS DISTRICT, CORPS OF ENGINEERS

FOR

GOVERNOR OF MISSOURI

SEPTEMBER 1979

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM

Name of Dam: Lost Lake Dam, Missouri Inv. No. 10212
State Located: Missouri
County Located: Lincoln
Stream: Lost Creek
Date of Inspection: June 15, 1979

Assessment of General Condition

Lost Lake Dam was inspected by the engineering firms of Consoer, Townsend and Associates LTD., and Engineering Consultants, Inc. (A Joint Venture) of St. Louis, Missouri using the "Recommended Guidelines for Safety Inspection of Dams". These guidelines were developed by the Chief of Engineers, U.S. Army, Washington, D.C., with the help of Federal and State agencies, professional engineering organizations, and private engineers. The resulting guidelines are considered to represent a consensus of the engineering profession.

The overall structural condition of the dam appears to be good. The dam does not exhibit signs of structural instability. The dam appears adequately maintained.


Based on the criteria in the guidelines, the dam is in the high hazard potential classification, which means that loss of life and appreciable property loss could occur in the event of failure of the dam. The estimated damage zone extends approximately 3.5 miles downstream of the dam. Within the damage zone are three dwellings, two buildings and a quarry and plant which may be subjected to flooding, with possible damage and/or destruction, and possible loss of life. The Lost Lake Dam is in the small size classification since it is less than 40 feet high and impounds less than 1,000 acre-feet of water.

Our inspection and evaluation indicate that the spillway of Lost Lake Dam does not meet the criteria set forth in the guidelines for a dam having the above size and hazard potential. Lost Lake Dam being a small size dam, with a high hazard potential, is required by the guidelines to pass from one-half Probable Maximum Flood to the Probable Maximum Flood without overtopping. Since there is high hazard potential downstream of the dam, the appropriate spillway design flood for this dam is the Probable Maximum Flood. It was determined that the reservoir/spillway system can accomodate 81 percent of the Probable Maximum Flood without overtopping the dam. Our evaluation indicates that the reservoir/spillway system will accomodate the 100-year flood without overtopping the dam.


The Probable Maximum Flood is defined as the flood discharge that may be expected from the most severe combination of critical meteorological and hydrologic conditions that are reasonably possible in the region. The 100-year flood is defined as a flood having a one percent chance of being equalled or exceeded during any given year.


Other conditions noted by the inspection team were: minor seepage at the principal spillway outlet; minor erosion on the upstream slope; tall grass growing around the principal spillway intake; and minor erosion near the crest at the left abutment.

The absence of seepage and stability analyses is a deficiency which should be corrected. Deficiency in the spillway capacity should also be corrected. Periodic inspections by a qualified engineer and establishing a maintenance log are recommended.



Walter G. Shifrin, P.E.





Overview of Lost Lake Dam

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM

LOST LAKE DAM, I.D. No. 10212

TABLE OF CONTENTS

<u>Sect. No.</u>	<u>Title</u>	<u>Page</u>
SECTION 1	PROJECT INFORMATION	1
	1.1 General	1
	1.2 Description of Project	3
	1.3 Pertinent Data	7
SECTION 2	ENGINEERING DATA	10
	2.1 Design	10
	2.2 Construction	10
	2.3 Operation	10
	2.4 Evaluation	11
SECTION 3	VISUAL INSPECTION	12
	3.1 Findings	12
	3.2 Evaluation	16

TABLE OF CONTENTS

(Continued)

<u>Sect. No.</u>	<u>Title</u>	<u>Page</u>
SECTION 4	OPERATION PROCEDURES	18
	4.1 Procedures	18
	4.2 Maintenance of Dam	18
	4.3 Maintenance of Operating Facilities	18
	4.4 Description of Any Warning System in Effect	19
	4.5 Evaluation	19
SECTION 5	HYDRAULIC/HYDROLOGIC	20
	5.1 Evaluation of Features	20
SECTION 6	STRUCTURAL STABILITY	24
	6.1 Evaluation of Structural Stability	24
SECTION 7	ASSESSMENT/REMEDIAL MEASURES	27
	7.1 Dam Assessment	27
	7.2 Remedial Measures	30

TABLE OF CONTENTS

(Continued)

LIST OF PLATES

	<u>Plate No.</u>
LOCATION MAP	1
PLAN AND ELEVATION OF DAM	2
DESIGN DRAWINGS	3-16
GEOLOGIC MAP	17
SEISMIC ZONE MAP	18

APPENDICES

APPENDIX A	-	PHOTOGRAPHS
APPENDIX B	-	HYDROLOGIC COMPUTATIONS

PHASE I INSPECTION REPORT
NATIONAL DAM SAFETY PROGRAM

LOST LAKE DAM, Missouri Inv. No. 10212

SECTION 1: PROJECT INFORMATION

1.1 General

a. Authority

The Dam Inspection Act, Public Law 92-367 of August, 1972, authorizes the Secretary of the Army, through the Corps of Engineers, to initiate a national program of dam inspections. Inspection for the Lost Lake Dam was carried out under Contract DACW 43-79-C-0075 to the Department of the Army, St. Louis District, Corps of Engineers, by the engineering firms of Consoer, Townsend & Associates Ltd., and Engineering Consultants, Inc. (A Joint Venture), of St. Louis, Missouri.

b. Purpose of Inspection

The visual inspection of the Lost Lake Dam was made on June 15, 1979. The purpose of the inspection was to make a general assessment as to the structural integrity and operational adequacy of the dam embankment and its appurtenant structures.

c. Scope of Report

This report summarizes available pertinent data relating to the project; presents a summary of visual observations made during the field inspection; presents an assessment of hydrologic and hydraulic conditions at the site; presents an assessment as to the structural adequacy of the various project features; and assesses the general condition of the dam with respect to safety.

Subsurface investigations, laboratory testing, and detailed analyses were not within the scope of this study. The conclusions drawn herein, therefore, are based on the presence of, or absence of, obvious signs of distress. No warranty as to the absolute safety of the project features is implied by the conclusions presented in this report.

It should be noted that reference in this report to left or right abutments is as viewed looking downstream. Where left abutment or left side of the dam is used in this report, this also refers to west abutment or side, and right to the east abutment or side.

d. Evaluation Criteria

Criteria used to evaluate the dam were furnished by the Department of the Army, Office of the Chief of Engineers, in "Recommended Guidelines for Safety Inspection of Dams", Appendix D. These guidelines were developed with the help of several Federal agencies and many State agencies, professional engineering organizations, and private engineers.

1.2 Description of the Project

a. Description of Dam and Appurtenances

The following description is based exclusively on the original design drawings, observations and measurements made during visual inspection. No "as-built" drawings were available during the preparation of this report.

The dam consists of a homogenous earthfill embankment between earthen abutments. The crest is 14 feet wide and 750 feet long as shown on available drawings. Field measurements show the crest length to be 788 feet. The crest elevation, according to the drawings, is 635.0 feet above MSL. From field measurements, the crest elevation was found to be 637.0 feet above MSL. The maximum height of the embankment is 33.5 feet.

The upstream and downstream slopes are 1V to 3H and 1V to 2H, respectively. According to the available drawings, an 8-foot wide berm was constructed on the upstream slope at an elevation of 617.0 feet above MSL.

A cutoff trench, with side slopes of 1V to 1H and a base width of 20 feet, was excavated parallel to the dam axis. According to Mr. Elmer Glosier, one of the owners of the dam, the trench was excavated to the rock foundation.

There are two spillways for the Lost Lake Reservoir. The principal spillway is located 100 feet to the east from the left abutment. The spillway is a 33-inch inside diameter reinforced concrete drop inlet structure which connects to a 24-inch inside diameter reinforced concrete pipe which passes under the embankment. According to the drawings,

the 24-inch reinforced concrete pipe is 148 feet long with a maximum slope of 8.4%. A 28-inch tall by 11-foot long concrete wall was constructed across the center of the drop inlet as an anti-vortex device. The concrete wall was constructed from the outside edge of the drop inlet across the opening of the drop inlet and into the embankment. A metal framework structure over the drop inlet was provided as a trashrack.

The emergency spillway is cut into the left abutment. The spillway is a grass-lined open channel with side slopes of 1V to 4H and a bottom width of 90 feet.

According to the plans, a 1-1/2-inch diameter galvanized steel pipe was provided as a livestock water supply. The intake is a low-water intake. The discharge control is a gate valve located 40 feet from the downstream end of the pipe. The gate valve is housed in a clay pipe.

A 6-inch diameter perforated helical metal pipe was provided in the embankment as an interceptor drain. The outlet of the drain is located 218 feet to the right of the centerline of the outlet to the drop inlet. According to the drawings, the drain was placed parallel to the crest extending 61 feet to the right of the drain outlet and 233 feet to the left of the drain outlet.

b. Location

The Lost Lake Dam is located on the headwaters of Lost Creek, Lincoln County, Missouri. The nearest downstream community is Elsberry, population 1,398, which is approximately 4.5 miles downstream. The dam and reservoir are shown on the Lockett Ridge Quadrangle Sheet (7.5 minute series) in Section 7, Township 50 North, Range 2 East.

c. Size Classification

According to the "Recommended Guidelines for Safety Inspection of Dams", by the U.S. Department of the Army, Office of the Chief Engineer, the dam is classified in the dam size category as being "Small" since its storage is less than 1,000 acre-feet. The dam is also classified as "Small" in dam height category because its height is less than 40 feet. The overall size classification is, accordingly, "Small" in size.

d. Hazard Classification

The dam has been classified as having "High" hazard potential in the National Inventory of Dams, on the basis that in the event of failure of the dam or its appurtenances, excessive damage could occur to downstream property, together with the possibility of the loss of life. Our findings concur with the classification. Within the estimated damage zone, which extends approximately 3.5 miles downstream of the dam, are three dwellings, two buildings, and a quarry and plant. The town of Elsberry is approximately 4.5 miles downstream.

e. Ownership

The Lost Lake Dam is owned privately by the Glosier Brothers. The mailing address is The Glosier Brothers, c/o Elmer Glosier, #5 Briarwood Lane, St. Charles, Missouri, 63301.

f. Purpose of Dam

The purpose of the dam is for flood control.

g. Design and Construction History

The available records show that the dam was designed in April 1955, by the Department of Agriculture, Soil Conservation Service as part of the Lost Creek Watershed Protection Project. The design engineer's name, as listed on the plans, is Mr. Browning. The dam was built in 1955-56 by Ray & Briscoe, a local construction company.

h. Normal Operational Procedures

Normal procedure is to allow the flood control reservoir to remain as full as possible with the water level being controlled by rainfall, runoff, evaporation and the elevation of the spillway crest.

1.3 Pertinent Data*

a. Drainage Area (square miles):	1.06
b. Discharge at Damsite	
Estimated experienced maximum flood (cfs):	60
Estimated ungated spillway capacity at maximum pool elevation (cfs):	5495
c. Elevation (Feet above MSL)	
Top of dam:	637
Spillway crest:	
Principal Spillway	617
Emergency Spillway	630.75
Normal Pool	617
Maximum Pool(PMF):	637.69
d. Reservoir	
Length of maximum pool (Feet):	2800
e. Storage (Acre-Feet)	
Top of dam:	669
Spillway crest:	
Principal Spillway	72
Emergency Spillway	414
Normal Pool:	72
Maximum Pool (PMF):	702
f. Reservoir Surface (Acres)	
Top of dam:	46
Spillway crest:	
Principal Spillway	15
Emergency Spillway	36

Normal Pool:	15
Maximum Pool(PMF):	46.5

g. Dam

Type:	Earthfill
Length:	788 feet
Structural Height:	33.5 feet
Hydraulic Height:	33.5 feet
Top width:	14.0 feet
Side slopes:	
Downstream	1V to 2H
Upstream	1V to 3H
Zoning:	Homogeneous
Impervious core:	NA
Cutoff:	Cutoff trench with 20-foot bottom width and 1V to 1H side slopes.
Grout curtain:	Unknown

h. Diversion and Regulating Tunnel None

i. Spillway

Type:	
Principal Spillway	Drop Inlet, Uncontrolled
Emergency Spillway	Open Channel, Uncontrolled
Length of weir:	
Principal Spillway	12.3 feet (Drop inlet spillway)
Emergency Spillway	90 feet
Crest Elevation (feet above MSL):	
Principal Spillway	617.0
Emergency Spillway	630.75

j. Regulating Outlets

Type:	1 1/2-inch diameter galvanized steel pipe livestock water supply
Length:	204 feet (According to Plans)
Closure:	Gate valve at downstream end
Maximum Capacity:	Unknown

* The term "maximum pool", as used in this section, refers to pool level at top of dam elevation unless otherwise specified.

SECTION 2 : ENGINEERING DATA

2.1 Design

Design drawings are available from the Department of Agriculture, Soil Conservation Service, and are included as part of this report. The drawings were prepared in April of 1955 by the Department of Agriculture, Soil Conservation Service. No specifications, engineering computations or soil data for this project were available. No "As-Built" drawings were available during the preparation of this report.

2.2 Construction

No data is available concerning the construction of the dam and appurtenant structures, other than the construction history given in Section 1.2g.

2.3 Operation

No operation records are available for the Lost Lake Dam.

2.4 Evaluation

a. Availability

The availability of engineering data is poor and consists only of the design drawings mentioned in Section 2.1, State Geological Maps and U.S.G.S. Quadrangle Sheets. "As-built" drawings, geologic and soil mechanics reports for this dam can be obtained from the Department of Agriculture, Soil Conservation Service. However, they were not available during the preparation of this report. No information on design hydrology, or hydraulic design was available, nor were seepage and stability analyses comparable to the requirements of the "Recommended Guidelines for Safety Inspection of Dams", which is considered a deficiency.

b. Adequacy

The conclusions presented in this report are based on field measurements, the available engineering data, past performance and present condition of the dam. The data available is inadequate to evaluate the hydraulic and hydrologic capabilities of the dam. In the absence of seepage and stability analyses no quantitative evaluation of the structural stability can be made.

c. Validity

Only a set of design drawings was available for review. From field measurements, the dam appears to have been constructed according to the available drawings, except for the discrepancies described in Section 1.2a. Lost Lake Dam was originally Flood Detention Structure No. 1 according to the design drawings provided by the Soil Conservation Service.

SECTION 3: VISUAL INSPECTION

3.1 Findings

a. General

A visual inspection of the Lost Lake Dam was made on June 15, 1979. The following persons were present during the inspection:

<u>Name</u>	<u>Affiliation</u>	<u>D. sciplines</u>
David J. Kerkes	Engineering Consultants, Inc.	Soils
Peter Howard	Engineering Consultants, Inc.	Geology
Mark R. Haynes	Engineering Consultants, Inc.	Civil, Structural and Mechanical
Kenneth L. Bullard	Engineering Consultants, Inc.	Hydraulics and Hydrology
Kevin Blume	Consoer, Townsend & Assoc., Ltd.	Civil and Structural
Elmer Glosier	Owner	
Robert Glosier	Owner	

Specific observations are discussed below.

b. Dam

The crest of the dam is well protected against surface erosion by a well maintained cover of grass. There was no evidence of significant settlement or cracking on the crest. No significant deviations in horizontal or vertical alignment were apparent. According to Mr. Robert Glosier, the water level has never been higher than 8 feet up the slope above the principal spillway. Therefore, the emergency spillway has not been used and the dam has not been overtopped.

The upstream slope had no evidence of riprap protection. Some minor erosion has occurred on the slope near the water surface due to wave action. According to Mr. Robert Glosier, the Glosier Brothers have tried to stop the erosion from doing further damage to the slope by planting canary reed grass along the shoreline. The slope appeared to be well maintained. No depressions or settlements were apparent on the slope.

The downstream slope of the embankment has a heavy grass cover. According to Mr. Elmer Glosier, a slide on the slope occurred shortly after construction. The slide area is located on the upper half of the slope and immediately to the right of the principal spillway outlet. The damaged area was approximately 20 to 25 feet wide and did not extend to the crest. The slide was shallow in depth. Some minor erosion was observed on the downstream embankment near the fence on the left abutment. No other depressions, bulges or settlements were apparent on the downstream slope. No seepage was apparent along the toe of the slope. Materials removed

immediately below the vegetation cover on the embankment appeared to be a clayey silt. The interceptor drain outlet was covered and the drain has not discharged to the best of Mr. Elmer Glosiers' knowledge.

According to the "Missouri General Soil Map and Soil Association Descriptions" published by the Soil Conservation Service, the materials in the general area of the dam are classified as a Lindley silt loam of the Central Mississippi Valley Wooded Slopes family. The Lindley silt may be susceptible to excessive erosion. If the Lindley silt was used in the embankment, the embankment may be susceptible to erosion and failure should overtopping result during a flood.

There are no signs of rodent activity in either the embankment or the abutments, but there is some muskrat activity in the reservoir area. According to Mr. Robert Glosier, the muskrats are trapped annually.

c. Project Geology

The dam is situated in the Dissect Till Plains Section of the Central Lowlands Province (Fenneman, N.M., "Physiography of Eastern United States", 1946). In the area of the dam site, however, much of the till has been removed by erosion. The entire area exhibits a karst topography with frequent sink holes.

The rocks in the area dip regionally to the northeast off the Ozark uplift to the south. Rocks ranging in age from Ordovician to Pennsylvanian occur in the general area.

At the dam site, limestones of the Plattin Formation (Ordovician) (Geologic Map of Missouri, 1979) occur. The rocks outcropping near the downstream toe consist of light gray, crystalline, dense limestone. The rock is massive and often forms escarpments of five feet or more. Higher stratigraphically, at about the elevation of the dam, a dense, gray sub-lithographic limestone crops out. No dip could be measured in the beds in the vicinity of the dam. The entire area exhibits a karst topography with frequent sink holes.

d. Appurtenant Structures

(1) Spillways

The concrete drop inlet structure is in good condition. No spalling or cracking of the concrete was observed. The trashrack was in good condition and unplugged. The concrete anti-vortex device was also in good condition with no spalling or cracking of the concrete observed. Leakage in the 24-inch diameter concrete pipe was detected. The leakage appeared to be in the drop inlet structure because the upstream invert of the structure had standing water in it. A flow of less than 1 gpm was observed at the outlet of the conduit. No spalling or cracking of the concrete in the conduit was observed. The joints of the exposed portion of the conduit showed no sign of misalignment. The area around the intake to the principal spillway was overgrown with tall grass.

The emergency spillway was heavily covered with grass. The emergency spillway channel was not obstructed. No indication of instability in the slopes was apparent. However, the slope on the left side of the spillway is being eroded by grazing cattle.

(2) Outlet Works

No regulated outlet works were provided for the Lost Lake Dam except for a livestock watering system. The inlet and outlet of the system were not located. The gate valve clay pipe housing was located at the toe of the downstream slope approximately 200 feet to the right of the principal spillway outlet. The gate valve was accessible, however, according to Mr. Elmer Glosier, the system is no longer used.

e. Reservoir Area

The water surface elevation was 616.8 feet above MSL on the day of the inspection.

The reservoir rim is gently sloped and no indication of instability or severe erosion were readily apparent. The slopes above the reservoir are heavily grassed. A few houses are built around the reservoir rim.

f. Downstream Channel

The downstream channel of the principal spillway is a well-defined, narrow rock lined channel. The channel was not obstructed. The channel extends for a few hundred feet downstream and then flows into an open grassy pasture.

The downstream channel of the emergency spillway is a well-defined, grass lined channel which was not obstructed. The channel is approximately 220 feet long and then it flows into an open grassy pasture.

3.2 Evaluation

The visual inspection did not reveal any items which are sufficiently significant to indicate a need for immediate remedial action.

The following conditions were observed which could affect the safety of the dam or which will require maintenance within a reasonable period of time.

1. Minor erosion of the upstream slope near the water surface.
2. Eroded area on the embankment near the left abutment.
3. The tall grass around the intake to the principal spillway.

SECTION 4: OPERATIONAL PROCEDURES

4.1 Procedures

Lost Lake Dam was built to impound water for flood control as part of the Lost Creek Watershed Protection Project. The only operating facility is a livestock watering system which, according to Mr. Elmer Glosier, is no longer used. The water level is controlled by rainfall, runoff, evaporation and the spillway crest elevation.

4.2 Maintenance of Dam

The dam is maintained by the owners, the Glosier Brothers. The maintenance of the dam appears to be adequate. The upstream slope and the crest are mowed semiannually, however, due to the steepness of the downstream slope, the downstream slope is not mowed. Trees and bushes are kept off of the embankment. There have not been any major repairs done to the dam itself since its original construction.

4.3 Maintenance of Operating Facilities

The only operational facility at the damsite is the livestock watering system. The livestock watering system is no longer used.

4.4 Description of Any Warning System in Effect

The inspection team was not informed of any warning system in effect for this dam.

4.5 Evaluation

The maintenance for Lost Lake Dam seems to be adequate, however, the remedial measures as described in Section 7 should be undertaken.

SECTION 5: HYDRAULIC/HYDROLOGIC

5.1 Evaluation of Features

a. Design

The watershed area of the Lost Lake Dam upstream from the dam axis consists of approximately 676 acres. Most of the watershed area is wooded and covered with grass. Land gradients in the higher regions of the watershed average roughly 12 percent, and in the lower areas surrounding the reservoir average about 6 percent. The Lost Lake Dam is located on the Lost Creek about 1.3 miles downstream of the extreme headwaters of the creek. At its longest arm the watershed is approximately 1.3 miles long. A drainage map showing the watershed area is presented as Plate 1 in Appendix B.

Evaluation of the hydraulic and hydrologic features of Lost Lake Dam was based on criteria set forth in the Corps of Engineers' "Recommended Guidelines for Safety Inspection of Dams", and additional guidance provided by the St. Louis District of the Corps of Engineers. The Probable Maximum Flood (PMF) was calculated from the Probable Maximum Precipitation (PMP) using the methods outlined in the U.S. Weather Bureau Publication, Hydrometeorological Report No. 33. The probable maximum storm duration was set at 24 hours, and storm rainfall distribution was based on criteria given in EM 1110-2-1411 (Standard Project Storm). The SCS method was used for deriving the unit hydrograph, utilizing the Corps of Engineers' computer program HEC-1 (Dam Safety Version). The unit

hydrograph parameters are presented in Appendix B. The SCS method was also used for determining loss rate. The hydrologic soil group of the watershed was determined by use of published soil maps. The hydrologic soil group of the watershed and the SCS curve number are also presented in Appendix B. The curve number, unit hydrograph parameters, PMF index rainfall and the percentages for various durations were directly input to the HEC-1 (Dam Safety Version) computer program to obtain the PMF hydrograph. The computed peak discharge of the PMF and one-half of the PMF are 10,568 cfs and 5,284 cfs, respectively.

Both the PMF and one-half of the PMF inflow hydrographs were routed through the reservoir by the Modified Puls Method also utilizing the HEC-1 (Dam Safety Version) computer program. The reservoir level was assumed at the principal spillway crest level at the start of the routing computation. The peak outflow discharges for the PMF and one-half of the PMF are 7,620 and 1,993 cfs, respectively. Only the PMF, when routed through the reservoir, results in overtopping of the dam.

The stage-outflow relation for the spillway was prepared from field notes and sketches prepared during the field inspection and limited design drawings. The reservoir stage-capacity data was based on the U.S.G.S. Luckett Ridge, Missouri Quadrangle topographic map (7.5 minute series). The spillway and overtop rating curve and the reservoir capacity curve are presented in Plates 2 & 3, respectively, in Appendix B.

From the standpoint of dam safety, the hydrologic design of a dam aims at avoiding overtopping. Overtopping is especially dangerous for an earth dam because the downrush of waters over the crest can erode the dam embankment and release all the stored water suddenly into the downstream floodplain. The safe hydrologic design of a dam requires a spillway crest height that can handle a very large and exceedingly rare flood without overtopping.

The Corps of Engineers designs its dams to safely pass the Probable Maximum Flood that is estimated could be generated from the upstream watershed. This is the generally accepted criterion for major dams throughout the world, and is the standard for dam safety where overtopping would pose any threat to human life. According to the Corps' criteria, the hydrologic requirement for safety for this dam is the capability to pass from one-half of the Probable Maximum Flood to the Probable Maximum Flood without overtopping.

b. Experience Data

No records of reservoir stage or spillway discharge are maintained for this site. Nevertheless, according to the owners, the maximum reservoir level was about 8 feet up the slope above the crest of the principal spillway.

c. Visual Observations

Observations made of the spillway during the visual inspection are discussed in Section 3.1c(1) and evaluated in Section 3.2.

d. Overtopping Potential

As indicated in Section 5.1-a, only the Probable Maximum Flood, when routed through the reservoir, results in overtopping of the dam. The PMF overtopped the dam crest by 0.69 feet. The spillway/reservoir system can accomodate one-half of the PMF with a freeboard of 2.88 feet. The total duration of embankment overflow is 0.42 hours during the PMF. The spillway and the reservoir of Lost Lake Dam are capable of accomodating a flood equal to approximately 81 percent of the PMF just before overtopping the dam. The 100-year flood is equal to approximately 15 percent of the PMF. The spillway/reservoir system will accomodate the 100-year flood without overtopping the dam.

The failure of the dam could cause extensive damage to the property downstream of the dam and possible loss of life. Within 3.1 miles downstream of the dam are three dwellings, two buildings and a quarry and plant. The town of Elsberry lies about 4.5 miles downstream.

SECTION 6: STRUCTURAL STABILITY

6.1 Evaluation of Structural Stability

a. Visual Observations

There were no signs of settlement or distress observed on the embankment or foundation during the visual inspection. The slide area on the downstream slope appears to be stable and is not serious enough to indicate an unsafe condition. According to Mr. Elmer Glosier, a professional engineer viewed the slide area shortly after the slide occurred. The professional engineer determined that the damaged area had no significant effect on the overall stability of the slope and that the slope had stabilized. According to Mr. Elmer Glosier, no other slides have occurred on the slope.

The minor erosion of the upstream slope due to wave action was not serious enough to constitute an unsafe condition. According to Mr. Robert Glosier, canary reed grass has been planted along the shoreline to prevent further erosion of the slope. Nevertheless, the erosion should be monitored and if the erosion continues, steps should be taken to control the problem.

Neither the principal spillway drop inlet nor the 24-inch reinforced concrete discharge pipe exhibited any evidence of misalignment or structural instability. The seepage observed at the outlet of the pipe is felt to have no significant effect on the structural stability of the dam. Nevertheless, the seepage should be monitored and any changes

in quantity or color should be reported and investigated.

The eroded area on the embankment near the left abutment was not serious enough to constitute an unsafe condition. The erosion of the left side slope of the emergency spillway does not constitute an unsafe condition because if the erosion is allowed to continue it will just erode into the natural ground. This condition will not decrease the emergency spillway discharge capacity or affect the stability of the side slopes of the spillway. Also, this condition will not cause any instability in the dam embankment.

b. Design and Construction Data

No design computations were uncovered during the report preparation phase. Seepage and stability analyses comparable to the requirements of the "Recommended Guidelines for Safety Inspection of Dams" was not available. No embankment or foundation soil parameters are available for carrying out a conventional stability analysis on the embankment. No construction data or specifications relating to the degree of embankment compaction are available for use in a stability analysis.

c. Operating Records

No operating records are available relating to the stability of the dam or appurtenant structures. The water level on the day of inspection was near the crest of the principal spillway, and it is assumed that the reservoir remains close to full at all times. No regulated outlet works exists at the damsite except for the livestock watering system. The system is no longer used.

d. Post Construction Changes

No post construction changes exist which will affect the structural stability of the dam.

e. Seismic Stability

The dam is located in seismic Zone 1, as defined in "Recommended Guidelines for Safety Inspection of Dams" as prepared by the Corps of Engineers, and therefore, does not require a seismic stability analysis.

SECTION 7: ASSESSMENT/REMEDIAL MEASURES

7.1 Dam Assessment

The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

It should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team.

It is also important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through continued care and inspection can there be any chance that an unsafe condition could be detected.

a. Safety

The spillway capacity of the Lost Lake Dam was found to be "Inadequate". The spillway/reservoir system will accommodate 81 percent of the PMF without overtopping the dam. The spillway and the reservoir will accommodate the 100-year flood without overtopping the dam.

The dam embankment appears to be in satisfactory structural condition. The minor erosion due to wave action on the upstream embankment slope is not serious at this time, however, the condition should be monitored and repaired as required.

The slide area on the downstream embankment slope has stabilized and was determined by a professional engineer to pose no danger to the stability of the downstream slope. No other signs of distress were observed in the embankment or in the foundation, nor was seepage observed at any location. No seepage and stability analyses were available for review.

The tall grass around the intake to the principal spillway should be cleared and not allowed to grow back. This condition poses an obstacle to the normal operation of the principal spillway. The seepage through the conduit of the principal spillway does not jeopardize the safety of the embankment in its present condition, but it should be monitored for any changes in quantity and color.

The erosion of the left side slope of the emergency spillway does not jeopardize the safety of the embankment in its present location. The erosion of the embankment near the left abutment does not pose any danger to the safety of the embankment in its present condition, but if allowed to continue to erode the embankment it could jeopardize the safety of the embankment.

The muskrat activity in the reservoir area poses no danger to the embankment, but they should be watched and not allowed to burrow into the embankment.

The Platten Formation is relatively competent and is a suitable foundation for the dam. While the possibility exists that leakage through solution channels could occur in such a limestone formation, it is evident that none occurs at this site at this time or that they were sufficiently blanketed during construction.

b. Adequacy of Information

The conclusions presented in this report are based on field measurements, the available engineering data, past performance and present condition of the dam. Information on the design hydrology, hydraulic design, and the operation and maintenance of the dam as well as seepage and stability analyses were not available. To supplement available data and allow for a more definite evaluation of the dam, it is recommended that the following programs be initiated:

1. Periodic inspection of the dam by a professional engineer experienced in the design and construction of earthen dams should be made and this inspection report made a matter of record.
2. Set up a maintenance schedule and log all visits to the dam for operation, repairs and maintenance.
3. Perform seepage and stability analyses comparable to the requirements of the "Recommended Guidelines for Safety Inspection of Dams".

c. Urgency

The remedial measures recommended in paragraph 7.2 should be accomplished within a reasonable period of time.

d. Necessity for Phase II Inspection

Based on results of the Phase I inspection, a Phase II inspection is not felt to be necessary.

7.2 Remedial Measures

Alternatives:

1. Spillway capacity and/or height of the dam should be increased to accomodate the PMF without overtopping the dam. The overtopping depth during the occurence of the PMF, stated elsewhere in the report is not the required or recommended increase in height of the the dam.

O & M Procedures:

1. The following corrective measures should be undertaken within a reasonable period of time.

- (a) Remove tall grass from around intake to the principal spillway and keep the grass from growing back.
- (b) Repair eroded area on the embankment near the crest at the left abutment and protect the area from further damage.

- (c) Seepage and stability analyses should be performed by a professional engineer experienced in the design and construction of dams.


2. The following conditions should be monitored.

- (a) Monitor erosion due to wave action on upstream slope, and if the erosion continues, other protective measures should be employed to protect the slope from further damage.
- (b) Monitor the seepage through the outlet conduit for changes in quantity or color and report any change.



3. The owner should initiate the following programs:

- (a) Periodic inspection of the dam by a professional engineer experienced in the design and construction of earthen dams.
- (b) Set up a maintenance schedule and log all visits to the dam for operation, repairs and maintenance.

PLATES



LOCATION MAP-LOST LAKE DAM



SCALE
1" = 200' (HORIZONTAL)
VERTICAL (NOT TO SCALE)


LOST LAKE DAM (MO. 10212)
PLAN & ELEVATION

U S DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

DETAIL PLANS FOR
LOST CREEK WATERSHED PROTECTION PROJECT

THE SOIL DISTRICT OF LINCOLN COUNTY, MISSOURI

PART I OF
MINOR WATERSHED "E"




FILE R2E


U. S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE



DETAIL PLANS FOR
ST CREEK WATERSHED PROTECTION PROJECT

THE SOIL DISTRICT OF LINCOLN COUNTY, MISSOURI

PART I OF
MINOR WATERSHED "E"







WORK LOCATION MAP
MINOR WATERSHED "E" PART I
U.S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE


Project: _____
Date: _____
Scale: _____
Map No. _____
Sheet No. _____


State Line	-----	Gravel	10
County Line	-----	Silt	11
Section Line	-----	Clay	12
Water Course	-----	Sandy clay loam	13
Water Course	-----	Sandy loam	14
Water Course	-----	Clay loam	15
Water Course	-----	Sandy clay	16
Water Course	-----	Clay	17
Water Course	-----	Sand	18
Water Course	-----	Fine gravel	19
Water Course	-----	Coarse gravel	20
Water Course	-----	Silt and shale	21
Water Course	-----	Silt and shale	22
Water Course	-----	Silt and shale	23
Water Course	-----	Silt and shale	24
Water Course	-----	Silt and shale	25
Water Course	-----	Silt and shale	26
Water Course	-----	Silt and shale	27
Water Course	-----	Silt and shale	28
Water Course	-----	Silt and shale	29
Water Course	-----	Silt and shale	30
Water Course	-----	Silt and shale	31
Water Course	-----	Silt and shale	32
Water Course	-----	Silt and shale	33
Water Course	-----	Silt and shale	34
Water Course	-----	Silt and shale	35
Water Course	-----	Silt and shale	36
Water Course	-----	Silt and shale	37
Water Course	-----	Silt and shale	38
Water Course	-----	Silt and shale	39
Water Course	-----	Silt and shale	40
Water Course	-----	Silt and shale	41
Water Course	-----	Silt and shale	42
Water Course	-----	Silt and shale	43
Water Course	-----	Silt and shale	44
Water Course	-----	Silt and shale	45
Water Course	-----	Silt and shale	46
Water Course	-----	Silt and shale	47
Water Course	-----	Silt and shale	48
Water Course	-----	Silt and shale	49
Water Course	-----	Silt and shale	50
Water Course	-----	Silt and shale	51
Water Course	-----	Silt and shale	52
Water Course	-----	Silt and shale	53
Water Course	-----	Silt and shale	54
Water Course	-----	Silt and shale	55
Water Course	-----	Silt and shale	56
Water Course	-----	Silt and shale	57
Water Course	-----	Silt and shale	58
Water Course	-----	Silt and shale	59
Water Course	-----	Silt and shale	60
Water Course	-----	Silt and shale	61
Water Course	-----	Silt and shale	62
Water Course	-----	Silt and shale	63
Water Course	-----	Silt and shale	64
Water Course	-----	Silt and shale	65
Water Course	-----	Silt and shale	66
Water Course	-----	Silt and shale	67
Water Course	-----	Silt and shale	68
Water Course	-----	Silt and shale	69
Water Course	-----	Silt and shale	70
Water Course	-----	Silt and shale	71
Water Course	-----	Silt and shale	72
Water Course	-----	Silt and shale	73
Water Course	-----	Silt and shale	74
Water Course	-----	Silt and shale	75
Water Course	-----	Silt and shale	76
Water Course	-----	Silt and shale	77
Water Course	-----	Silt and shale	78
Water Course	-----	Silt and shale	79
Water Course	-----	Silt and shale	80
Water Course	-----	Silt and shale	81
Water Course	-----	Silt and shale	82
Water Course	-----	Silt and shale	83
Water Course	-----	Silt and shale	84
Water Course	-----	Silt and shale	85
Water Course	-----	Silt and shale	86
Water Course	-----	Silt and shale	87
Water Course	-----	Silt and shale	88
Water Course	-----	Silt and shale	89
Water Course	-----	Silt and shale	90
Water Course	-----	Silt and shale	91
Water Course	-----	Silt and shale	92
Water Course	-----	Silt and shale	93
Water Course	-----	Silt and shale	94
Water Course	-----	Silt and shale	95
Water Course	-----	Silt and shale	96
Water Course	-----	Silt and shale	97
Water Course	-----	Silt and shale	98
Water Course	-----	Silt and shale	99
Water Course	-----	Silt and shale	100



- II**
1. Peat
 2. Silt loam
 3. Silty clay loam
 4. Silty clay loam
 5. Silty clay loam
 6. Silty clay loam
 7. Silty clay loam
 8. Silty clay loam
 9. Silty clay loam
 10. Silty clay loam
 11. Silty clay loam
 12. Silty clay loam
 13. Silty clay loam
 14. Silty clay loam
 15. Silty clay loam
 16. Silty clay loam
 17. Silty clay loam
 18. Silty clay loam
 19. Silty clay loam
 20. Silty clay loam
 21. Silty clay loam
 22. Silty clay loam
 23. Silty clay loam
 24. Silty clay loam
 25. Silty clay loam
 26. Silty clay loam
 27. Silty clay loam
 28. Silty clay loam
 29. Silty clay loam
 30. Silty clay loam
 31. Silty clay loam
 32. Silty clay loam
 33. Silty clay loam
 34. Silty clay loam
 35. Silty clay loam
 36. Silty clay loam
 37. Silty clay loam
 38. Silty clay loam
 39. Silty clay loam
 40. Silty clay loam
 41. Silty clay loam
 42. Silty clay loam
 43. Silty clay loam
 44. Silty clay loam
 45. Silty clay loam
 46. Silty clay loam
 47. Silty clay loam
 48. Silty clay loam
 49. Silty clay loam
 50. Silty clay loam
 51. Silty clay loam
 52. Silty clay loam
 53. Silty clay loam
 54. Silty clay loam
 55. Silty clay loam
 56. Silty clay loam
 57. Silty clay loam
 58. Silty clay loam
 59. Silty clay loam
 60. Silty clay loam
 61. Silty clay loam
 62. Silty clay loam
 63. Silty clay loam
 64. Silty clay loam
 65. Silty clay loam
 66. Silty clay loam
 67. Silty clay loam
 68. Silty clay loam
 69. Silty clay loam
 70. Silty clay loam
 71. Silty clay loam
 72. Silty clay loam
 73. Silty clay loam
 74. Silty clay loam
 75. Silty clay loam
 76. Silty clay loam
 77. Silty clay loam
 78. Silty clay loam
 79. Silty clay loam
 80. Silty clay loam
 81. Silty clay loam
 82. Silty clay loam
 83. Silty clay loam
 84. Silty clay loam
 85. Silty clay loam
 86. Silty clay loam
 87. Silty clay loam
 88. Silty clay loam
 89. Silty clay loam
 90. Silty clay loam
 91. Silty clay loam
 92. Silty clay loam
 93. Silty clay loam
 94. Silty clay loam
 95. Silty clay loam
 96. Silty clay loam
 97. Silty clay loam
 98. Silty clay loam
 99. Silty clay loam
 100. Silty clay loam

* Dashed lines indicate existing contours or gully banks within a cut of excavation, etc.
 NOTE: These symbols are used primarily on the more detailed maps, where applicable they may be shown on the plans.





DIVERSIONS & EMERGENCY SPILLWAYS

DEFINITIONS OF TERMS

- a - grade of channel inlet or drop perpendicular to length
- b - bottom width of channel inlet
- c - side slope width, from toe to toe
- d - top width of channel inlet
- e - height of structure above base line

TABLE OF STANDARD DIMENSIONS

Improvement	7	55
Improved Drainage	6	31
Drainage	6	31
Leaves	6	31 or As shown on plans
Drop Inlet Embankments	6	31 or As shown on plans
Gate Embankments	6	31
Drop Spillway Embankments	6	31 upstream - 21 downstream

Note 1. Use standard dimensions unless otherwise shown on plans
2. Use a, b, and FH as shown on plans

GENERAL NOTES

- Improvements are along Base Line unless otherwise indicated
- Elevations of pipes refer to invert elevations
- Gross section shown as looking downstream
- Lines showing limits of structure excavation are on a 1:1 slope unless otherwise indicated




1. Rock
2. Peat
3. Silt loam
4. Silty clay loam
5. Sandy loam
6. Clay loam
7. Sandy clay
8. Clay
9. Sand
10. Fine gravel
11. Coarse gravel
12. Silt and shale
13. Limestone
14. Sandstone
15. Limestone
16. Glacial drift (perennial)
17. Glacial drift (perennial)


Using either the designation number, number or symbol representing the soil type

Method No. 2
Using Mechanical Analysis
(gravel, sand, silt, clay)
0-10-76-6
0-28-64-8
0-20-65-14

LEGEND



CROSS SECTION LEGEND



LEGEND & INFORMATION


U.S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

3-P 43776



Note: All Points Located
By Camera

1. 1000' Contour
2. 1000' Contour
3. 1000' Contour
4. 1000' Contour
5. 1000' Contour
6. 1000' Contour
7. 1000' Contour
8. 1000' Contour
9. 1000' Contour
10. 1000' Contour



M.P. OF S.W. DE



Cemetery not included within water shed

1. All pits dug with back hoe
approximately 2' in dia. by 2' deep
2. All pits are dug with
with 1/2" Auger Co. 1
3. All pits are dug lower
of pits and springs
4. All pits are dug for logs and bones

MAP OF SUB-PLAC EXPLORATION

Scale 1:2500

SOIL TWO 50M P2E

FLOOD DETENTION STRUCTURE No 1

Need Sub-surface Explorations

U.S. DEPARTMENT OF AGRICULTURE

SOIL CONSERVATION SERVICE

Project No. 1-1000-10000

Location: 1-1000-10000

Scale: 1:2500

Date: 1-1000-10000

Prepared by: 1-1000-10000

Checked by: 1-1000-10000

Approved by: 1-1000-10000

Project No. 1-1000-10000

Location: 1-1000-10000

Scale: 1:2500

Date: 1-1000-10000

Prepared by: 1-1000-10000

Checked by: 1-1000-10000

Approved by: 1-1000-10000

8

Water tank and pressure
line



Water tank and pressure
line

Water tank and pressure
line



Water tank and pressure
line

Water tank and pressure
line

Water tank and pressure
line

Water tank and pressure
line

Water tank and pressure
line

Water tank and pressure
line

Water tank and pressure
line

Water tank and pressure
line

Water tank and pressure
line

Water tank and pressure
line

Water tank and pressure
line


Water tank and pressure
line

Water tank and pressure
line

Water tank and pressure
line




SECTION 8.8




SOIL CULTIVATION CHART	
DATE	
TIME	
LOCATION	
PLANT	
SOIL	
WATER	
TEMPERATURE	
WIND	
MOISTURE	
PH	
EC	
EC2	
EC3	
EC4	
EC5	
EC6	
EC7	
EC8	
EC9	
EC10	
EC11	
EC12	
EC13	
EC14	
EC15	
EC16	
EC17	
EC18	
EC19	
EC20	
EC21	
EC22	
EC23	
EC24	
EC25	
EC26	
EC27	
EC28	
EC29	
EC30	
EC31	
EC32	
EC33	
EC34	
EC35	
EC36	
EC37	
EC38	
EC39	
EC40	
EC41	
EC42	
EC43	
EC44	
EC45	
EC46	
EC47	
EC48	
EC49	
EC50	
EC51	
EC52	
EC53	
EC54	
EC55	
EC56	
EC57	
EC58	
EC59	
EC60	
EC61	
EC62	
EC63	
EC64	
EC65	
EC66	
EC67	
EC68	
EC69	
EC70	
EC71	
EC72	
EC73	
EC74	
EC75	
EC76	
EC77	
EC78	
EC79	
EC80	
EC81	
EC82	
EC83	
EC84	
EC85	
EC86	
EC87	
EC88	
EC89	
EC90	
EC91	
EC92	
EC93	
EC94	
EC95	
EC96	
EC97	
EC98	
EC99	
EC100	

1. The trench is to be 10 feet wide and 4 feet deep. The trench is to be 10 feet wide and 4 feet deep. The trench is to be 10 feet wide and 4 feet deep.




**PLAN
GENERAL LAYOUT**

The trench is to be 10 feet wide and 4 feet deep. The trench is to be 10 feet wide and 4 feet deep. The trench is to be 10 feet wide and 4 feet deep.



ANTI SEEP COLLAR



ANTI SEEP COLLAR

STOCK WATERING 3-3-20 25-01-1

LIST OF MATERIAL	
1. Trench 10 ft wide	1000
2. Trench 10 ft wide	1000
3. Trench 10 ft wide	1000
4. Trench 10 ft wide	1000
5. Trench 10 ft wide	1000
6. Trench 10 ft wide	1000
7. Trench 10 ft wide	1000
8. Trench 10 ft wide	1000
9. Trench 10 ft wide	1000
10. Trench 10 ft wide	1000
11. Trench 10 ft wide	1000
12. Trench 10 ft wide	1000
13. Trench 10 ft wide	1000
14. Trench 10 ft wide	1000
15. Trench 10 ft wide	1000
16. Trench 10 ft wide	1000
17. Trench 10 ft wide	1000
18. Trench 10 ft wide	1000
19. Trench 10 ft wide	1000
20. Trench 10 ft wide	1000
21. Trench 10 ft wide	1000
22. Trench 10 ft wide	1000
23. Trench 10 ft wide	1000
24. Trench 10 ft wide	1000
25. Trench 10 ft wide	1000
26. Trench 10 ft wide	1000
27. Trench 10 ft wide	1000
28. Trench 10 ft wide	1000
29. Trench 10 ft wide	1000
30. Trench 10 ft wide	1000
31. Trench 10 ft wide	1000
32. Trench 10 ft wide	1000
33. Trench 10 ft wide	1000
34. Trench 10 ft wide	1000
35. Trench 10 ft wide	1000
36. Trench 10 ft wide	1000
37. Trench 10 ft wide	1000
38. Trench 10 ft wide	1000
39. Trench 10 ft wide	1000
40. Trench 10 ft wide	1000
41. Trench 10 ft wide	1000
42. Trench 10 ft wide	1000
43. Trench 10 ft wide	1000
44. Trench 10 ft wide	1000
45. Trench 10 ft wide	1000
46. Trench 10 ft wide	1000
47. Trench 10 ft wide	1000
48. Trench 10 ft wide	1000
49. Trench 10 ft wide	1000
50. Trench 10 ft wide	1000
51. Trench 10 ft wide	1000
52. Trench 10 ft wide	1000
53. Trench 10 ft wide	1000
54. Trench 10 ft wide	1000
55. Trench 10 ft wide	1000
56. Trench 10 ft wide	1000
57. Trench 10 ft wide	1000
58. Trench 10 ft wide	1000
59. Trench 10 ft wide	1000
60. Trench 10 ft wide	1000
61. Trench 10 ft wide	1000
62. Trench 10 ft wide	1000
63. Trench 10 ft wide	1000
64. Trench 10 ft wide	1000
65. Trench 10 ft wide	1000
66. Trench 10 ft wide	1000
67. Trench 10 ft wide	1000
68. Trench 10 ft wide	1000
69. Trench 10 ft wide	1000
70. Trench 10 ft wide	1000
71. Trench 10 ft wide	1000
72. Trench 10 ft wide	1000
73. Trench 10 ft wide	1000
74. Trench 10 ft wide	1000
75. Trench 10 ft wide	1000
76. Trench 10 ft wide	1000
77. Trench 10 ft wide	1000
78. Trench 10 ft wide	1000
79. Trench 10 ft wide	1000
80. Trench 10 ft wide	1000
81. Trench 10 ft wide	1000
82. Trench 10 ft wide	1000
83. Trench 10 ft wide	1000
84. Trench 10 ft wide	1000
85. Trench 10 ft wide	1000
86. Trench 10 ft wide	1000
87. Trench 10 ft wide	1000
88. Trench 10 ft wide	1000
89. Trench 10 ft wide	1000
90. Trench 10 ft wide	1000
91. Trench 10 ft wide	1000
92. Trench 10 ft wide	1000
93. Trench 10 ft wide	1000
94. Trench 10 ft wide	1000
95. Trench 10 ft wide	1000
96. Trench 10 ft wide	1000
97. Trench 10 ft wide	1000
98. Trench 10 ft wide	1000
99. Trench 10 ft wide	1000
100. Trench 10 ft wide	1000

THE DEPARTMENT OF THE ARMY
OFFICE OF THE SECRETARY OF THE ARMY

1. [Illegible]
2. [Illegible]
3. [Illegible]
4. [Illegible]
5. [Illegible]
6. [Illegible]
7. [Illegible]
8. [Illegible]
9. [Illegible]
10. [Illegible]

11. [Illegible]
12. [Illegible]
13. [Illegible]
14. [Illegible]
15. [Illegible]
16. [Illegible]
17. [Illegible]
18. [Illegible]
19. [Illegible]
20. [Illegible]

21. [Illegible]
22. [Illegible]
23. [Illegible]
24. [Illegible]
25. [Illegible]
26. [Illegible]
27. [Illegible]
28. [Illegible]
29. [Illegible]
30. [Illegible]

31. [Illegible]
32. [Illegible]
33. [Illegible]
34. [Illegible]
35. [Illegible]
36. [Illegible]
37. [Illegible]
38. [Illegible]
39. [Illegible]
40. [Illegible]

41. [Illegible]
42. [Illegible]
43. [Illegible]
44. [Illegible]
45. [Illegible]
46. [Illegible]
47. [Illegible]
48. [Illegible]
49. [Illegible]
50. [Illegible]

51. [Illegible]
52. [Illegible]
53. [Illegible]
54. [Illegible]
55. [Illegible]
56. [Illegible]
57. [Illegible]
58. [Illegible]
59. [Illegible]
60. [Illegible]

61. [Illegible]
62. [Illegible]
63. [Illegible]
64. [Illegible]
65. [Illegible]
66. [Illegible]
67. [Illegible]
68. [Illegible]
69. [Illegible]
70. [Illegible]

71. [Illegible]
72. [Illegible]
73. [Illegible]
74. [Illegible]
75. [Illegible]
76. [Illegible]
77. [Illegible]
78. [Illegible]
79. [Illegible]
80. [Illegible]

81. [Illegible]
82. [Illegible]
83. [Illegible]
84. [Illegible]
85. [Illegible]
86. [Illegible]
87. [Illegible]
88. [Illegible]
89. [Illegible]
90. [Illegible]

91. [Illegible]
92. [Illegible]
93. [Illegible]
94. [Illegible]
95. [Illegible]
96. [Illegible]
97. [Illegible]
98. [Illegible]
99. [Illegible]
100. [Illegible]

100 100

See Spec. 100

CONCRETE
Anti-void Concrete
No. 100 Base - 2.00 Co. 78

STOCK WATER SYSTEM DETAILS

U.S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

DATE: 7-10-68 BY: [illegible]
PROJECT NO.: 39437-0

STOCK WATERING SYSTEM DETAILS




DIMENSIONS		STEEL QUANTITIES				CONCRETE		
R/C	SECTION	Bar	Total	Weight	Total	Footings	Wall	Deck
DAN	5							
1								
2								
3								
4								
5								
6								
7								
8								
9								
10								
11								
12								
13								
14								
15								
16								
17								
18								
19								
20								
21								
22								
23								
24								
25								
26								
27								
28								
29								
30								
31								
32								
33								
34								
35								
36								
37								
38								
39								
40								
41								
42								
43								
44								
45								
46								
47								
48								
49								
50								
51								
52								
53								
54								
55								
56								
57								
58								
59								
60								
61								
62								
63								
64								
65								
66								
67								
68								
69								
70								
71								
72								
73								
74								
75								
76								
77								
78								
79								
80								
81								
82								
83								
84								
85								
86								
87								
88								
89								
90								
91								
92								
93								
94								
95								
96								
97								
98								
99								
100								



SECTION B-B



SECTION A-A



SECTION C-C


STEEL QUANTITIES

Item	Unit	Quantity	Weight	Notes
1. Steel Pipe	ft	120.0	120.0	
2. Steel Plate	sq ft	10.0	10.0	
3. Steel Reinforcement	lb	100.0	100.0	
4. Steel Brackets	each	10.0	10.0	
5. Steel Bolts	each	10.0	10.0	
6. Steel Nuts	each	10.0	10.0	
7. Steel Washers	each	10.0	10.0	
8. Steel Spacers	each	10.0	10.0	
9. Steel Anchors	each	10.0	10.0	
10. Steel Hangers	each	10.0	10.0	
11. Steel Supports	each	10.0	10.0	
12. Steel Brackets	each	10.0	10.0	
13. Steel Bolts	each	10.0	10.0	
14. Steel Nuts	each	10.0	10.0	
15. Steel Washers	each	10.0	10.0	
16. Steel Spacers	each	10.0	10.0	
17. Steel Anchors	each	10.0	10.0	
18. Steel Hangers	each	10.0	10.0	
19. Steel Supports	each	10.0	10.0	
20. Steel Brackets	each	10.0	10.0	
21. Steel Bolts	each	10.0	10.0	
22. Steel Nuts	each	10.0	10.0	
23. Steel Washers	each	10.0	10.0	
24. Steel Spacers	each	10.0	10.0	
25. Steel Anchors	each	10.0	10.0	
26. Steel Hangers	each	10.0	10.0	
27. Steel Supports	each	10.0	10.0	
28. Steel Brackets	each	10.0	10.0	
29. Steel Bolts	each	10.0	10.0	
30. Steel Nuts	each	10.0	10.0	
31. Steel Washers	each	10.0	10.0	
32. Steel Spacers	each	10.0	10.0	
33. Steel Anchors	each	10.0	10.0	
34. Steel Hangers	each	10.0	10.0	
35. Steel Supports	each	10.0	10.0	
36. Steel Brackets	each	10.0	10.0	
37. Steel Bolts	each	10.0	10.0	
38. Steel Nuts	each	10.0	10.0	
39. Steel Washers	each	10.0	10.0	
40. Steel Spacers	each	10.0	10.0	
41. Steel Anchors	each	10.0	10.0	
42. Steel Hangers	each	10.0	10.0	
43. Steel Supports	each	10.0	10.0	
44. Steel Brackets	each	10.0	10.0	
45. Steel Bolts	each	10.0	10.0	
46. Steel Nuts	each	10.0	10.0	
47. Steel Washers	each	10.0	10.0	
48. Steel Spacers	each	10.0	10.0	
49. Steel Anchors	each	10.0	10.0	
50. Steel Hangers	each	10.0	10.0	
51. Steel Supports	each	10.0	10.0	
52. Steel Brackets	each	10.0	10.0	
53. Steel Bolts	each	10.0	10.0	
54. Steel Nuts	each	10.0	10.0	
55. Steel Washers	each	10.0	10.0	
56. Steel Spacers	each	10.0	10.0	
57. Steel Anchors	each	10.0	10.0	
58. Steel Hangers	each	10.0	10.0	
59. Steel Supports	each	10.0	10.0	
60. Steel Brackets	each	10.0	10.0	
61. Steel Bolts	each	10.0	10.0	
62. Steel Nuts	each	10.0	10.0	
63. Steel Washers	each	10.0	10.0	
64. Steel Spacers	each	10.0	10.0	
65. Steel Anchors	each	10.0	10.0	
66. Steel Hangers	each	10.0	10.0	
67. Steel Supports	each	10.0	10.0	
68. Steel Brackets	each	10.0	10.0	
69. Steel Bolts	each	10.0	10.0	
70. Steel Nuts	each	10.0	10.0	
71. Steel Washers	each	10.0	10.0	
72. Steel Spacers	each	10.0	10.0	
73. Steel Anchors	each	10.0	10.0	
74. Steel Hangers	each	10.0	10.0	
75. Steel Supports	each	10.0	10.0	
76. Steel Brackets	each	10.0	10.0	
77. Steel Bolts	each	10.0	10.0	
78. Steel Nuts	each	10.0	10.0	
79. Steel Washers	each	10.0	10.0	
80. Steel Spacers	each	10.0	10.0	
81. Steel Anchors	each	10.0	10.0	
82. Steel Hangers	each	10.0	10.0	
83. Steel Supports	each	10.0	10.0	
84. Steel Brackets	each	10.0	10.0	
85. Steel Bolts	each	10.0	10.0	
86. Steel Nuts	each	10.0	10.0	
87. Steel Washers	each	10.0	10.0	
88. Steel Spacers	each	10.0	10.0	
89. Steel Anchors	each	10.0	10.0	
90. Steel Hangers	each	10.0	10.0	
91. Steel Supports	each	10.0	10.0	
92. Steel Brackets	each	10.0	10.0	
93. Steel Bolts	each	10.0	10.0	
94. Steel Nuts	each	10.0	10.0	
95. Steel Washers	each	10.0	10.0	
96. Steel Spacers	each	10.0	10.0	
97. Steel Anchors	each	10.0	10.0	
98. Steel Hangers	each	10.0	10.0	
99. Steel Supports	each	10.0	10.0	
100. Steel Brackets	each	10.0	10.0	

CONCRETE QUANTITIES


Item	Unit	Quantity	Weight	Notes
1. Concrete	cu yd	10.0	10.0	
2. Gravel	cu yd	10.0	10.0	
3. Sand	cu yd	10.0	10.0	
4. Cement	lb	100.0	100.0	
5. Water	gal	10.0	10.0	
6. Steel Reinforcement	lb	100.0	100.0	
7. Steel Brackets	each	10.0	10.0	
8. Steel Bolts	each	10.0	10.0	
9. Steel Nuts	each	10.0	10.0	
10. Steel Washers	each	10.0	10.0	
11. Steel Spacers	each	10.0	10.0	
12. Steel Anchors	each	10.0	10.0	
13. Steel Hangers	each	10.0	10.0	
14. Steel Supports	each	10.0	10.0	
15. Steel Brackets	each	10.0	10.0	
16. Steel Bolts	each	10.0	10.0	
17. Steel Nuts	each	10.0	10.0	
18. Steel Washers	each	10.0	10.0	
19. Steel Spacers	each	10.0	10.0	
20. Steel Anchors	each	10.0	10.0	
21. Steel Hangers	each	10.0	10.0	
22. Steel Supports	each	10.0	10.0	
23. Steel Brackets	each	10.0	10.0	
24. Steel Bolts	each	10.0	10.0	
25. Steel Nuts	each	10.0	10.0	
26. Steel Washers	each	10.0	10.0	
27. Steel Spacers	each	10.0	10.0	
28. Steel Anchors	each	10.0	10.0	
29. Steel Hangers	each	10.0	10.0	
30. Steel Supports	each	10.0	10.0	
31. Steel Brackets	each	10.0	10.0	
32. Steel Bolts	each	10.0	10.0	
33. Steel Nuts	each	10.0	10.0	
34. Steel Washers	each	10.0	10.0	
35. Steel Spacers	each	10.0	10.0	
36. Steel Anchors	each	10.0	10.0	
37. Steel Hangers	each	10.0	10.0	
38. Steel Supports	each	10.0	10.0	
39. Steel Brackets	each	10.0	10.0	
40. Steel Bolts	each	10.0	10.0	
41. Steel Nuts	each	10.0	10.0	
42. Steel Washers	each	10.0	10.0	
43. Steel Spacers	each	10.0	10.0	
44. Steel Anchors	each	10.0	10.0	
45. Steel Hangers	each	10.0	10.0	
46. Steel Supports	each	10.0	10.0	
47. Steel Brackets	each	10.0	10.0	
48. Steel Bolts	each	10.0	10.0	
49. Steel Nuts	each	10.0	10.0	
50. Steel Washers	each	10.0	10.0	
51. Steel Spacers	each	10.0	10.0	
52. Steel Anchors	each	10.0	10.0	
53. Steel Hangers	each	10.0	10.0	
54. Steel Supports	each	10.0	10.0	
55. Steel Brackets	each	10.0	10.0	
56. Steel Bolts	each	10.0	10.0	
57. Steel Nuts	each	10.0	10.0	
58. Steel Washers	each	10.0	10.0	
59. Steel Spacers	each	10.0	10.0	
60. Steel Anchors	each	10.0	10.0	
61. Steel Hangers	each	10.0	10.0	
62. Steel Supports	each	10.0	10.0	
63. Steel Brackets	each	10.0	10.0	
64. Steel Bolts	each	10.0	10.0	
65. Steel Nuts	each	10.0	10.0	
66. Steel Washers	each	10.0	10.0	
67. Steel Spacers	each	10.0	10.0	
68. Steel Anchors	each	10.0	10.0	
69. Steel Hangers	each	10.0	10.0	
70. Steel Supports	each	10.0	10.0	
71. Steel Brackets	each	10.0	10.0	
72. Steel Bolts	each	10.0	10.0	
73. Steel Nuts	each	10.0	10.0	
74. Steel Washers	each	10.0	10.0	
75. Steel Spacers	each	10.0	10.0	
76. Steel Anchors	each	10.0	10.0	
77. Steel Hangers	each	10.0	10.0	
78. Steel Supports	each	10.0	10.0	
79. Steel Brackets	each	10.0	10.0	
80. Steel Bolts	each	10.0	10.0	
81. Steel Nuts	each	10.0	10.0	
82. Steel Washers	each	10.0	10.0	
83. Steel Spacers	each	10.0	10.0	
84. Steel Anchors	each	10.0	10.0	
85. Steel Hangers	each	10.0	10.0	
86. Steel Supports	each	10.0	10.0	
87. Steel Brackets	each	10.0	10.0	
88. Steel Bolts	each	10.0	10.0	
89. Steel Nuts	each	10.0	10.0	
90. Steel Washers	each	10.0	10.0	
91. Steel Spacers	each	10.0	10.0	
92. Steel Anchors	each	10.0	10.0	
93. Steel Hangers	each	10.0	10.0	
94. Steel Supports	each	10.0	10.0	
95. Steel Brackets	each	10.0	10.0	
96. Steel Bolts	each	10.0	10.0	
97. Steel Nuts	each	10.0	10.0	
98. Steel Washers	each	10.0	10.0	
99. Steel Spacers	each	10.0	10.0	
100. Steel Anchors	each	10.0	10.0	

R/C
PIPE
O AM




PLAN

SECTION A-A




STANDARD DETAILS FOR CANTILEVER R/C PIPE OUTLET

U.S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE




DETAILS OF EXPANSION JOINT AND TYPE II CRADLE




SECTION A-A

PREC




DETAILS OF EXPANSION JOINT AND TYPE III CRADLE




SECTION B-B

Drawn at
scale of 1/4" = 1'-0"
(Dimensions may be
made with a scale of
1/4" = 1'-0" or 1/8" = 1'-0")

Also provide
interior
and exterior
of each




ELEVATION OF ANTI-SEEP COLLAR




SECTION ON E


(REINFORCED CONCRETE DROP INLET 24" DIA) DETAILS OF TYPE 2, 3 CRADLE, ANTI-SEEP COLL				
U.S. DEPARTMENT OF AGRICULTURE SOIL CONSERVATION SERVICE				
PROJECT NO.				
DISTRICT OFFICE		REGIONAL OFFICE		
DATE	DRAWN	CHECKED	DATE	SCALE
10/1/57	J. W.	J. W.	10/1/57	1:1



SECTION ON CENTERLINE




REAR ELEVATION




Every rail is bolted to structure
by 1/2" dia. through 1/2" dia. 3/4" dia.
UNIT 1 & only section do not to structure

PLAN



FRONT ELEVATION

Item	Quantity	Unit	Material
1	1	ea	Steel
2	1	ea	Steel
3	1	ea	Steel
4	1	ea	Steel
5	1	ea	Steel
6	1	ea	Steel
7	1	ea	Steel
8	1	ea	Steel
9	1	ea	Steel
10	1	ea	Steel
11	1	ea	Steel
12	1	ea	Steel
13	1	ea	Steel
14	1	ea	Steel
15	1	ea	Steel
16	1	ea	Steel
17	1	ea	Steel
18	1	ea	Steel
19	1	ea	Steel
20	1	ea	Steel
21	1	ea	Steel
22	1	ea	Steel
23	1	ea	Steel
24	1	ea	Steel
25	1	ea	Steel
26	1	ea	Steel
27	1	ea	Steel
28	1	ea	Steel
29	1	ea	Steel
30	1	ea	Steel
31	1	ea	Steel
32	1	ea	Steel
33	1	ea	Steel
34	1	ea	Steel
35	1	ea	Steel
36	1	ea	Steel
37	1	ea	Steel
38	1	ea	Steel
39	1	ea	Steel
40	1	ea	Steel
41	1	ea	Steel
42	1	ea	Steel
43	1	ea	Steel
44	1	ea	Steel
45	1	ea	Steel
46	1	ea	Steel
47	1	ea	Steel
48	1	ea	Steel
49	1	ea	Steel
50	1	ea	Steel
51	1	ea	Steel
52	1	ea	Steel
53	1	ea	Steel
54	1	ea	Steel
55	1	ea	Steel
56	1	ea	Steel
57	1	ea	Steel
58	1	ea	Steel
59	1	ea	Steel
60	1	ea	Steel
61	1	ea	Steel
62	1	ea	Steel
63	1	ea	Steel
64	1	ea	Steel
65	1	ea	Steel
66	1	ea	Steel
67	1	ea	Steel
68	1	ea	Steel
69	1	ea	Steel
70	1	ea	Steel
71	1	ea	Steel
72	1	ea	Steel
73	1	ea	Steel
74	1	ea	Steel
75	1	ea	Steel
76	1	ea	Steel
77	1	ea	Steel
78	1	ea	Steel
79	1	ea	Steel
80	1	ea	Steel
81	1	ea	Steel
82	1	ea	Steel
83	1	ea	Steel
84	1	ea	Steel
85	1	ea	Steel
86	1	ea	Steel
87	1	ea	Steel
88	1	ea	Steel
89	1	ea	Steel
90	1	ea	Steel
91	1	ea	Steel
92	1	ea	Steel
93	1	ea	Steel
94	1	ea	Steel
95	1	ea	Steel
96	1	ea	Steel
97	1	ea	Steel
98	1	ea	Steel
99	1	ea	Steel
100	1	ea	Steel




QUANTITIES

STEEL	2	45' 10"	76
	3	18'	6
	4	20'	13
	5	31' 75"	13


BILL OF MATERIAL FOR GUARD RAIL

ITEM	DESCRIPTION	LENGTH
1	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
2	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
3	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
4	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
5	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
6	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
7	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
8	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
9	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
10	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
11	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
12	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
13	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
14	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
15	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
16	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
17	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
18	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
19	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
20	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
21	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
22	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
23	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
24	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
25	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
26	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
27	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
28	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
29	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
30	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
31	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
32	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
33	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
34	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
35	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
36	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
37	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
38	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
39	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
40	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
41	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
42	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
43	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
44	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
45	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
46	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
47	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
48	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
49	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
50	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
51	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
52	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
53	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
54	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
55	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
56	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
57	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
58	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
59	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
60	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
61	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
62	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
63	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
64	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
65	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
66	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
67	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
68	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
69	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
70	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
71	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
72	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
73	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
74	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
75	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
76	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
77	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
78	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
79	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
80	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
81	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
82	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
83	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
84	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
85	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
86	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
87	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
88	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
89	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
90	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
91	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
92	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
93	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
94	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
95	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
96	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
97	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
98	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
99	1/2" x 1/2" x 1/2" Steel Angle	4' 5"
100	1/2" x 1/2" x 1/2" Steel Angle	4' 5"


BAR TYPE DETAILS



REAR ELEVATION



PLAN



CONSTRUCTION NOTE

1. All steel sections must be made of steel.

2. All steel sections must be made of steel.

3. All steel sections must be made of steel.

4. All steel sections must be made of steel.

5. All steel sections must be made of steel.

6. All steel sections must be made of steel.

7. All steel sections must be made of steel.

8. All steel sections must be made of steel.



Construction Note: Metal forms are available at the St. Charles County Jail District Office located at St. Charles, Missouri, and can be rented for a nominal fee.

MODIFICATION NO. 1 28 APRIL 1955

CONCRETE CIRCULAR RISER FOR 24" DIA. R/C PIPE

U. S. DEPARTMENT OF AGRICULTURE
SOIL CONSERVATION SERVICE

ATTENTION: Local Creek Watershed Protection Agency
at St. Charles, Missouri, at 223 S. 1st St.
Eastwood, Missouri
Telephone: 223-1111
Project: 223-1111
Date: 223-1111
Sheet: 223-1111




- END HANDED PAGE 4 -

1. *Chrysomelids*
2. *Chrysomelids*
3. *Chrysomelids*
4. *Chrysomelids*
5. *Chrysomelids*
6. *Chrysomelids*
7. *Chrysomelids*
8. *Chrysomelids*
9. *Chrysomelids*
10. *Chrysomelids*
11. *Chrysomelids*
12. *Chrysomelids*
13. *Chrysomelids*
14. *Chrysomelids*
15. *Chrysomelids*
16. *Chrysomelids*
17. *Chrysomelids*
18. *Chrysomelids*
19. *Chrysomelids*
20. *Chrysomelids*
21. *Chrysomelids*
22. *Chrysomelids*
23. *Chrysomelids*
24. *Chrysomelids*
25. *Chrysomelids*
26. *Chrysomelids*
27. *Chrysomelids*
28. *Chrysomelids*
29. *Chrysomelids*
30. *Chrysomelids*
31. *Chrysomelids*
32. *Chrysomelids*
33. *Chrysomelids*
34. *Chrysomelids*
35. *Chrysomelids*
36. *Chrysomelids*
37. *Chrysomelids*
38. *Chrysomelids*
39. *Chrysomelids*
40. *Chrysomelids*
41. *Chrysomelids*
42. *Chrysomelids*
43. *Chrysomelids*
44. *Chrysomelids*
45. *Chrysomelids*
46. *Chrysomelids*
47. *Chrysomelids*
48. *Chrysomelids*
49. *Chrysomelids*
50. *Chrysomelids*
51. *Chrysomelids*
52. *Chrysomelids*
53. *Chrysomelids*
54. *Chrysomelids*
55. *Chrysomelids*
56. *Chrysomelids*
57. *Chrysomelids*
58. *Chrysomelids*
59. *Chrysomelids*
60. *Chrysomelids*
61. *Chrysomelids*
62. *Chrysomelids*
63. *Chrysomelids*
64. *Chrysomelids*
65. *Chrysomelids*
66. *Chrysomelids*
67. *Chrysomelids*
68. *Chrysomelids*
69. *Chrysomelids*
70. *Chrysomelids*
71. *Chrysomelids*
72. *Chrysomelids*
73. *Chrysomelids*
74. *Chrysomelids*
75. *Chrysomelids*
76. *Chrysomelids*
77. *Chrysomelids*
78. *Chrysomelids*
79. *Chrysomelids*
80. *Chrysomelids*
81. *Chrysomelids*
82. *Chrysomelids*
83. *Chrysomelids*
84. *Chrysomelids*
85. *Chrysomelids*
86. *Chrysomelids*
87. *Chrysomelids*
88. *Chrysomelids*
89. *Chrysomelids*
90. *Chrysomelids*
91. *Chrysomelids*
92. *Chrysomelids*
93. *Chrysomelids*
94. *Chrysomelids*
95. *Chrysomelids*
96. *Chrysomelids*
97. *Chrysomelids*
98. *Chrysomelids*
99. *Chrysomelids*
100. *Chrysomelids*

22/04/2022

Examinations to be held in the month of May 1917.



U.S. DEPARTMENT OF AGRICULTURE	
SOIL CONSERVATION SERVICE	
OFFICE OF THE DISTRICT ENGINEER	
WASHINGTON, D.C.	
DATE: _____	
BY: _____	
CHECKED BY: _____	
APPROVED BY: _____	

540

74.13

84.40

57.50

41.10

24.10

11.10

0.10

74.13

84.40

57.50

41.10

24.10

11.10

0.10

620

600

580

74.13

84.40

57.50

41.10

24.10

11.10

0.10

620

600

580

74.13

84.40

57.50

41.10


24.10

11.10

0.10

Section 27.5

Section 27.5



KING COUNTY			
STA 85+30 TO STA 9+91 GULLY A			
- see Appendix 2, Part 1			
U.S. DEPARTMENT OF AGRICULTURE			
SOIL CONSERVATION SERVICE			
PROJECT: LOSS OF CREEK - WATERS-25 PART 1			
DATE: 1-1-54			
BY: [Signature]			
Drawn by	Checked by	Reviewed by	Date
1-1-54	1-1-54	1-1-54	1-1-54
3 P 4377-C			

62.5

1000

62.5

62.5

62.5

62.5

62.5

62.5

62.5

62.5

62.5

62.5

62.5

62.5

62.5

62.5

62.5

1

1000

1000

1000

1000

1

1000

1000

1000

1000

1000

1000

62.5

62.5

62.5

62.5

62.5

62.5

62.5

62.5

62.5


62.5

62.5

62.5

62.5

62.5



CROSS SECTION			
STATION 100 TO 120 ON E. SIDE			
U.S. DEPARTMENT OF AGRICULTURE			
SOIL CONSERVATION SERVICE			
DATE: 10-1-55			
DRAWN BY: J. H. H.			
CHECKED BY: J. H. H.			
APPROVED BY: J. H. H.			
SCALE: 1" = 10'			

640

620

600

620

600

620

600

620

600

620

600

620

Sta 5

Sta 10

Sta 15

Sta 20

Sta 25

640

620

640

620

600

640


620

600


80

80

2000



CROSS SECTIONS			
STA. 8+50 TO STA. 9+40 ON E. F. L.			
U.S. DEPARTMENT OF AGRICULTURE			
SOIL CONSERVATION SERVICE			
DATE: 11/17/57			
BY: [Signature]			



QUATERNARY — Qal - ALLUVIAN

SILURIAN — S - SILURIAN UNDIVIDED

PENNSYLVANIAN — Pcc - CHEROKEE GROUP

MISSISSIPPIAN {
 Mm - MERAMECIAN SERIES
 Mo - OSAGEAN SERIES
 Mk - KINDERHOOKIAN SERIES,
 CHOTEAU GROUP

ORDOVICIAN


Omk {
 NOIX LIMESTONE
 MAQUOKETA SHALE
 CAPE LIMESTONE
 KIMMSWICK FORMATION
 Odp {
 DECORAH FORMATION
 PLATTIN FORMATION
 Osp - ST. PETER'S
 SANDSTONE

DEVONIAN — DEVONIAN UNDIVIDED

X - LOCATION OF DAM , MO. 10212

REFERENCE :
 GEOLOGIC MAP OF MISSOURI ,
 MISSOURI GEOLOGIC SURVEY ,
 a) 1961 , b) 1979

GEOLOGIC MAP
 OF
 LINCOLN COUNTY
 AND
 ADJACENT AREA



APPENDIX A

PHOTOGRAPHS TAKEN DURING INSPECTION

OVERVIEW




PHOTO INDEX
FOR
LOST LAKE DAM

Lost Lake Dam

- Photo 1. - View of the crest of the embankment.
- Photo 2. - View of the downstream embankment slope.
- Photo 3. - View of the upstream embankment slope.
- Photo 4. - View of the intake to drop inlet structure.
- Photo 5. - View of the outlet of the 24-inch diameter concrete conduit.
- Photo 6. - View of the discharge channel of the 24-inch diameter concrete conduit.
- Photo 7. - View of the emergency spillway on the left abutment.
- Photo 8. - View of the emergency spillway on the left abutment.
- Photo 9. - View of the reservoir rim.

Lost Lake Dam



Photo 1



Photo 2

Lost Lake Dam



Photo 3



Photo 4

Lost Lake Dam



Photo 5



Photo 6

Lost Lake Dam



Photo 7



Photo 8

Lost Lake Dam





Photo 9

APPENDIX B

HYDROLOGIC COMPUTATIONS

PLATE 1, APPENDIX B



CONTOUR INTERVAL 20 FEET
DATUM IS MEAN SEA LEVEL
DRAINAGE BOUNDARY - - - - -

LOST LAKE DAM (MO 10212)
DRAINAGE BASIN

DAM SAFETY INSPECTION ~ UTAH

SHEET NO. 1 OF


LOST LAKE DAM # 10212

JOB NO. 1240

SPILLWAY AND OVERTOP RATING CURVE

BY DNZ DATE 6/21/79
418 6-26-79

Y_c	A_c	T_c	$K = 50 \sqrt{A}$	$K^2/2g$	$Q_c = A_c V_c$	$V_c + K^2/2g + 650.75$	C_d	L_c	H_c	$Q_c = C_d L_c H_c^{3/2}$	$Q_c = Q_c + Q_s$
0	0	0	0	0	0	650.75	-	-	-	-	0
1	94	98	5.6	0.5	522.0	632.25	-	-	-	-	632.25
2	196	106	7.71	0.92	1511.2	633.7	-	-	-	-	1511.2
3	306	114	9.3	1.3	2842.6	635.1	-	-	-	-	2842.6
4	424	122	10.6	1.7	4481.8	636.5	-	-	-	-	4481.8
4.25	454.6	123.9	10.9	1.8	4937.2	636.8	-	-	-	-	4937.2
5	550	130	11.7	2.1	6414.4	637.9	2.64	708	.9	1776.2	8191
6.25	718.8	140	12.8	2.6	9234.6	639.6	2.53	700	2.6	8688.4	17923
5.5	616	134	12.2	2.3	7480.6	638.6	2.63	700	1.6	4194.3	11683



DAM SAFETY INSPECTION - MISSOURI


SHEET NO. 2 OF

LOST LAKE DAM (10212)

JOB NO. 1240-001

PRINCIPAL SPILOWAY RATING CURVE

BY H&B DATE 6-21-68



MEASUREMENTS FROM SCS PLANS
AND CHECKED IN THE FIELD.
WHERE POSSIBLE.

PRINCIPAL SPILOWAY DISCHARGE (ASSUME NO TAILWATER EFFECT)

AT W.L. = 617.5

a) WEIR FLOW ASSUME $C = 3.03$

$$L = \pi D = \pi \times 3.92 = 12.33'$$

$$H = 617.5 - 612.0 = 0.5$$

$$Q = CLH^{3/2} = 3.03 \times 12.33' \times 0.5^{3/2} = 13 \text{ CFS}$$

b) CHECK FOR PRESSURE FLOW: (Neglect friction in the drop pipe)

$$H_f = \left(1 + K_e + f \frac{L}{D}\right) \frac{V^2}{2g}$$

$$\text{ASSUME } e = 0.005, \frac{e}{D} = 0.0025 \Rightarrow f = 0.025; \text{ ASSUME } K_e = 0.5$$

DAM SAFETY INSPECTION - MISSOURI

SHEET NO. 3 OF

LOST LAKE DAM (10212)

JOB NO. 1240-001

PRINCIPAL SPIGWAY DISCHARGE

BY HLB DATE 6-21-79

$$H_T = \left(1 + 0.5 + 0.025 \frac{148}{2}\right) \frac{V^2}{2g}$$

$$H_T = 3.35 \frac{V^2}{2g} \Rightarrow V = 4.38 \sqrt{H_T}$$

$$Q = A \cdot V = \pi \frac{D^2}{4} \times 4.38 \sqrt{H_T} = \pi \frac{9}{4} \times 4.38 \sqrt{H_T}$$

$$Q = 13.77 \sqrt{H_T}$$

$$H_T = 617.5 - 601.0 = 16.5$$

$$Q = 13.77 \sqrt{16.5} = 56 \text{ CFS.}$$

∴ AT ELEV. 617.5 WEIR FLOW CONTROLS

AND $Q = 13 \text{ CFS.}$

$$\text{AT W.L.} = 618.0 \quad H = 618.0 - 601.0 = 1.0$$

a) WEIR FLOW,

$$Q = CLH^{3/2} = 3.03 \times 12.83 \times 1^{3/2} = 37 \text{ CFS.}$$

b) PRESSURE FLOW

$$Q = 13.77 \sqrt{H_T}, \quad H_T = 618 - 601 = 17$$

$$Q = 13.77 \sqrt{17} = 57 \text{ CFS.}$$

∴ AT ELEV. 618, WEIR FLOW CONTROLS

AND $Q = 37 \text{ CFS.}$

DAM SAFETY INSPECTION - MISSOURI

SHEET NO. 4 OF

LOST LAKE DAM (10212)

JOB NO. 1240-001

PRINCIPAL SPILLWAY DISCHARGE

BY KLB DATE 6-21-79

$$\text{AT. W.L.} = 619, H = 619 - 617 = 2$$

a) WEIR FLOW

$$Q = CLH^{3/2} = 3.03 \times 12.33 \times 2^{3/2} = 106 \text{ CFS}$$

b) PRESSURE FLOW, $H_f = 619 - 601 = 18$

$$Q = 13.77 \sqrt{H_f} = 13.77 \sqrt{18} = 58 \text{ CFS}$$

 \therefore AT W.L. = 619 PRESSURE FLOW CONTROLSAND $Q = 58 \text{ CFS}$.

ALSO FOR ALL ELEVATIONS ABOVE 619
PRESSURE FLOW WILL CONTROL
AND THE EQUATION

$$Q = 13.77 \sqrt{H_f} \text{ WILL BE USED}$$

DAM SAFETY INSPECTION - MISSOURI

SHEET NO. 5 OF

LOST LAKE DAM (10212)

JOB NO. 1240-001

SPILLWAY AND OVERTOP RATING CURVE


BY HLB DATE 6-31-79

COMBINED RATING CURVE TABULATION

RESERVOIR WATER SURFACE ELEV.	H _F	PRINCIPAL SPILLWAY DISCHARGE $Q = 13.87 H^{3/2}$	EMERGENCY SPILLWAY DISCHARGE	DISCHARGE OVER TOP OF DAM	COMBINED DISCHARGE
617.0	16.0	-	-	-	0
617.5	16.5	13*	-	-	13
618.0	17.0	37*	-	-	37
619.0	18.0	58	-	-	58
623.0	22.0	65	-	-	65
628.0	27	72	-	-	72
630.75	29.75	75	-	-	75
632.25	31.25	77	522	-	599
633.7	32.7	79	1511	-	1590
635.1	34.1	80	2,843	-	2,923
636.5	35.5	82	4,484	-	4,564
636.8	35.8	82	4,937	-	5,019
637.9	36.9	84	6,414	1,776	8,274
638.6	37.6	84	7,489	4,194	11,767

* WEIR FLOW CONTROLS.

PLATE 2, APPENDIX B



LOST LAKE DAM (MO. 10212)
SPILLWAY & OVERTOP RATING CURVE

Dam Safety Inspection - Missouri

SHEET NO. 1 OF

LOST LAKE Dam - #10912


JOB NO. 1246

Reservoir Area Capacity

BY M.R.H. DATE 5-30-
D.N.E.V.LOST LAKE DAMReservoir Area Capacity

Elev. M.S.L. (Ft.)	Reservoir Surface Area (Acres)	Incremental Volume (Ac.-Ft.)	Total Volume (Ac.-Ft.)	Remarks
605	0	0	0	Est. Streambed at Dam
614	11	33.0	33.	W.S. as shown on Quadrangle.
617	15	38.8	72	PRINCIPAL SPIWAY CREST EL. AS SHOWN ON PLANS
620	19	50.9	123	AREA MEASURED ON USGS MAP
630.75	36	290.8	414	EMERGENCY SPIWAY CREST
637	46	255.6	669.1	TOP OF DAM
640	51	145.4	815	AREA MEASURED ON USGS MAP.

PLATE-3, APPENDIX - B



LOST LAKE DAM (MO. 10212)
RESERVOIR CAPACITY CURVE

AO-A104 620

CONSOER TOWNSEND AND ASSOCIATES LTD ST LOUIS MO
NATIONAL DAM SAFETY PROGRAM. LOST LAKE DAM (M010212), MISSISSIP--ETC(U)
SEP 79 W 6 SHIPRIN


F/6 13/13

DACW43-79-C-0075

NL

UNCLASSIFIED

2 of 2
A
DOHCO



END
DATE
FILMED
40-81
DTIC

DAM SAFETY INSPECTION - MISSOURI

SHEET NO. 1 OF

LOST LAKE DAM # MO 10212

JOB NO. 1240

PROBABLE MAXIMUM PRECIPITATION

BY DNZ

DATE 6/9/79

KLB

6/23/79

LOST LAKE DAM # MO 10212

DETERMINATION OF PMP

1. DETERMINE DRAINAGE AREA OF BASIN

D. A. = 676 ACRES

2. DETERMINE PMP INDEX RAINFALL (200 SQ. MI + 24 HRS DUR.)

LOCATION OF CENTROID BASIN

LONG. = 90° 48' 41" LAT. = 39° 06' 30"


⇒ PMP = 24.7" (From Fig. 1, HMR #33)

3. DETERMINE BASIN RAINFALL IN TERMS OF PERCENTAGE OF PMP INDEX RAINFALL FOR VARIOUS DURATIONS:

LOCATION LONG. = 90° 48' 41" LAT. = 39° 06' 30"

⇒ ZONE 7

DURATION (HOURS)	PERCENT OF INDEX RAINFALL	TOTAL RAINFALL (IN.)	RAINFALL INCREMENTS (IN.)	DURATION OF INCREMENTS
6	100	24.7	24.7	6
12	120	29.6	4.9	6
24	130	32.1	2.5	12



PMP FOR 200 SQ MI +
24 HRS DURATION = 24.7"

DAM NO. 10212

LOCATION OF CENTROID
OF WATERSHED:

AT 39°06'30" LONG 90°48'41"











FIGURE 2
SEASONAL VARIATION
DEPTH-AREA-DURATION RELATIONSHIPS
Percentage to be applied to 200 square miles
24 hour probable maximum precipitation values
for: THE-ALL SEASON ENVELOPE

DAM SAFETY INSPECTION - MISSOURI

SHEET NO. 1 OF

LOST LAKE DAM # MO. 10212

JOB NO. 1240

UNIT HYDROGRAPH PARAMETERS

BY DNZ

DATE 6/11/79

KLG 6/22/79

1. DRAINAGE AREA, $A = 676 \text{ ACRES} = 1.06 \text{ SQ MI.}$
2. LENGTH OF STREAM, $L = 1.33 \text{ MI} = 7022 \text{ FE}$
3. ELEVATION AT DRAINAGE DIVIDE ALONG LONGEST STREAM.
 $H_1 = 945 \text{ FE}$
4. RESERVOIR ELEVATION AT SPILLWAY CREST, $H_2 = 617 \text{ FE}$
5. DIFFERENCE IN ELEVATION, $\Delta H = 328 \text{ FE}$
6. AVERAGE SLOPE OF STREAM = $\frac{\Delta H}{L} = \frac{328}{7022} = 4.67\%$
7. TIME OF CONCENTRATION:

a) BY KIRPICH FORMULA:

$$T_c = \left(\frac{11.9 \times L^3}{\Delta H} \right)^{0.385} = \left(\frac{11.9 \times 1.33^3}{331} \right)^{0.385} = 0.39 \text{ HR}$$

b) BY VELOCITY ESTIMATE: AVG VEL = 4.0 FPS

$$T_c = \frac{L}{V} = \frac{7022}{4(60 \times 60)} = 0.49 \text{ HR}$$

USE $T_c = 0.39$

$$8. \text{ LAG TIME, } L_t = 0.6 \times 0.39 = 0.23$$

$$9. \text{ UNIT DURATION, } D \leq \frac{L_t}{3} = \frac{0.23}{3} = 0.077 < 0.083$$

USE $D = 0.083$

$$10. \text{ TIME TO PEAK, } T_p = \frac{D}{2} + L_t = \frac{0.083}{2} + 0.23 = 0.272$$

$$11. \text{ PEAK DISCHARGE, } q_p = \frac{484 A}{T_p} = \frac{484 (1.06)}{0.272}$$

$$q_p = 1886 \text{ CFS}$$

DAM SAFETY INSPECTION / MISSOURI

SHEET NO. 1 OF

LOST LAKE DAM (MO. 10212)

JOB NO. 1240-001

HYDROLOGIC SOIL GROUP & CURVE NUMBER

BY MAS DATE 7/11/78

LOST LAKE DAM (MO. 10212)DETERMINATION OF HYDROLOGIC SOIL GROUP & SCS CURVE NUMBER

1. Watershed soils consist of group B and C soils. Soil group B seems to be predominant. Assume soil group B for the entire watershed.
2. Most of the watershed is wooded and covered with grass. Assume hydrologic condition of the watershed to be "Fair" for infiltration purpose.

Thus $CN = 60$ for AMC-II & group B soil. $\Rightarrow CN = 78$ for AMC-III & group B soil.

DAM SAFETY INSPECTION - MISSOURI

SHEET NO. 1 OF

LOST LAKE DAM - (#10312)

JOB NO. 1240-001

100 YR FLOOD FROM REGRESSION EQUATION

BY KLB

DATE 6-22-71

V MAS

LOST LAKE DAM100 YR FLOOD FROM REGRESSION EQUATION.REGRESSION EQUATION FOR 100-YR FLOOD
FOR MISSOURI:

$$Q_{100} = 85.1 A^{0.934} S^{0.576}$$

WHERE

A = DRAINAGE AREA IN SQ. MI.

S = MAIN CHANNEL SLOPE FE/MI
(AVG. SLOPE BETWEEN D.I.L. AND D.B.L.)

FOR LOST LAKE DAM:

A = 1.06 SQ. MI.

S = 142 FE/MI.

$$Q_{100} = 85.1 (1.06)^{0.934} (142)^{0.576}$$

$$Q_{100} = 1560 \text{ CFS.}$$

HEC1DB INPUT DATA

[illegible]

PREVIEW OF SEQUENCE OF STREAM NETWORK CALCULATIONS

RUNOFF HYDROGRAPH AT 10212
ROUTE HYDROGRAPH TO 10312
END OF NETWORK

INFLOW PMF AND ONE-HALF PMF HYDROGRAPHS

.....
 FLOOD HYDROGRAPH PACKAGE (HEC-1)
 DAN SAFETY VERSION JULY 1974
 LAST MODIFICATION 26 FEB 75

RUN DATE: 79/07/13,
 TIME: 11.47.33.

DAN SAFETY INSPECTION - HQ 5000J
 100% LAKE OAK (100%)
 ONE AND 50 PERCENT OF DETERMINATION AND ROUTING

JOB SPECIFICATION									
NO	NAME	ICAY	IMR	IMR	ICAY	ICPT	ICPT	ICPT	ICPT
500		0	0	0	0	0	0	0	0
		0	0	0	0	0	0	0	0

MULTI-STEP ANALYSIS TO BE PERFORMED
 UPLAND FLOODING SOLUTION 1
 M1050 11.00 11.50

.....

AREA FLOOD COMPUTATION

INPUT PRECIPITATION INDEX, RATIO, AND UNIT HYDROGRAPH RESULTS

ICAY	ICPT	ICAY	ICPT	ICAY	ICPT	ICAY	ICPT	ICAY	ICPT
10012	10012	10012	10012	10012	10012	10012	10012	10012	10012

HYDROGRAPH DATA									
INVDG	INVDG	INVDG	INVDG	INVDG	INVDG	INVDG	INVDG	INVDG	INVDG
1	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00

PEAK DATA									
SPFE	SPFE	SPFE	SPFE	SPFE	SPFE	SPFE	SPFE	SPFE	SPFE
0.10	24.70	100.00	120.00	130.00	140.00	150.00	160.00	170.00	180.00

LOSS DATA									
INVDG	INVDG	INVDG	INVDG	INVDG	INVDG	INVDG	INVDG	INVDG	INVDG
1	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00	1.00

CURVE NO. 1 100% OF FLOOD 100% OF FLOOD 100% OF FLOOD 100% OF FLOOD 100% OF FLOOD 100% OF FLOOD 100% OF FLOOD 100% OF FLOOD 100% OF FLOOD 100% OF FLOOD

.....

PRECIPITATION DATA

.....

.....

MO:DA	HR:MN	PERIOD	RAIN	EXCS	LOSS	COMP O	IND-OF-PERIOD FLOW	MO:DA	HR:MN	PERIOD	RAIN	EXCS	LOSS	COMP
1-01	05	1	.01	0.00	.01	0	1-01 12:45	151	.21	.19	.02	1940.		
1-01	10	2	.01	0.00	.01	0	1-01 13:00	152	.21	.19	.02	1978.		
1-01	15	3	.01	0.00	.01	0	1-01 13:15	153	.21	.19	.02	1984.		
1-01	20	4	.01	0.00	.01	0	1-01 13:30	154	.21	.19	.02	1992.		
1-01	25	5	.01	0.00	.01	0	1-01 13:45	155	.21	.19	.02	1999.		
1-01	30	6	.01	0.00	.01	0	1-01 14:00	156	.21	.19	.02	2005.		
1-01	35	7	.01	0.00	.01	0	1-01 14:15	157	.25	.23	.02	2011.		
1-01	40	8	.01	0.00	.01	0	1-01 14:30	158	.25	.23	.02	2017.		
1-01	45	9	.01	0.00	.01	0	1-01 14:45	159	.25	.23	.02	2023.		
1-01	50	10	.01	0.00	.01	0	1-01 15:00	160	.25	.23	.02	2029.		
1-01	55	11	.01	0.00	.01	0	1-01 15:15	161	.25	.23	.02	2035.		
1-01	00	12	.01	0.00	.01	0	1-01 15:30	162	.25	.23	.02	2041.		
1-01	05	13	.01	0.00	.01	0	1-01 15:45	163	.25	.23	.02	2047.		
1-01	10	14	.01	0.00	.01	0	1-01 16:00	164	.25	.23	.02	2053.		
1-01	15	15	.01	0.00	.01	0	1-01 16:15	165	.25	.23	.02	2059.		
1-01	20	16	.01	0.00	.01	0	1-01 16:30	166	.25	.23	.02	2065.		
1-01	25	17	.01	0.00	.01	0	1-01 16:45	167	.25	.23	.02	2071.		
1-01	30	18	.01	0.00	.01	0	1-01 17:00	168	.25	.23	.02	2077.		
1-01	35	19	.01	0.00	.01	0	1-01 17:15	169	.25	.23	.02	2083.		
1-01	40	20	.01	0.00	.01	0	1-01 17:30	170	.25	.23	.02	2089.		
1-01	45	21	.01	0.00	.01	0	1-01 17:45	171	.25	.23	.02	2095.		
1-01	50	22	.01	0.00	.01	0	1-01 18:00	172	.25	.23	.02	2101.		
1-01	55	23	.01	0.00	.01	0	1-01 18:15	173	.25	.23	.02	2107.		
1-01	00	24	.01	0.00	.01	0	1-01 18:30	174	.25	.23	.02	2113.		
1-01	05	25	.01	0.00	.01	0	1-01 18:45	175	.25	.23	.02	2119.		
1-01	10	26	.01	0.00	.01	0	1-01 19:00	176	.25	.23	.02	2125.		
1-01	15	27	.01	0.00	.01	0	1-01 19:15	177	.25	.23	.02	2131.		
1-01	20	28	.01	0.00	.01	0	1-01 19:30	178	.25	.23	.02	2137.		
1-01	25	29	.01	0.00	.01	0	1-01 19:45	179	.25	.23	.02	2143.		
1-01	30	30	.01	0.00	.01	0	1-01 20:00	180	.25	.23	.02	2149.		
1-01	35	31	.01	0.00	.01	0	1-01 20:15	181	.25	.23	.02	2155.		
1-01	40	32	.01	0.00	.01	0	1-01 20:30	182	.25	.23	.02	2161.		
1-01	45	33	.01	0.00	.01	0	1-01 20:45	183	.25	.23	.02	2167.		
1-01	50	34	.01	0.00	.01	0	1-01 21:00	184	.25	.23	.02	2173.		
1-01	55	35	.01	0.00	.01	0	1-01 21:15	185	.25	.23	.02	2179.		
1-01	00	36	.01	0.00	.01	0	1-01 21:30	186	.25	.23	.02	2185.		
1-01	05	37	.01	0.00	.01	0	1-01 21:45	187	.25	.23	.02	2191.		
1-01	10	38	.01	0.00	.01	0	1-01 22:00	188	.25	.23	.02	2197.		
1-01	15	39	.01	0.00	.01	0	1-01 22:15	189	.25	.23	.02	2203.		
1-01	20	40	.01	0.00	.01	0	1-01 22:30	190	.25	.23	.02	2209.		
1-01	25	41	.01	0.00	.01	0	1-01 22:45	191	.25	.23	.02	2215.		
1-01	30	42	.01	0.00	.01	0	1-01 23:00	192	.25	.23	.02	2221.		
1-01	35	43	.01	0.00	.01	0	1-01 23:15	193	.25	.23	.02	2227.		
1-01	40	44	.01	0.00	.01	0	1-01 23:30	194	.25	.23	.02	2233.		
1-01	45	45	.01	0.00	.01	0	1-01 23:45	195	.25	.23	.02	2239.		
1-01	50	46	.01	0.00	.01	0	1-01 24:00	196	.25	.23	.02	2245.		
1-01	55	47	.01	0.00	.01	0	1-01 24:15	197	.25	.23	.02	2251.		
1-01	00	48	.01	0.00	.01	0	1-01 24:30	198	.25	.23	.02	2257.		
1-01	05	49	.01	0.00	.01	0	1-01 24:45	199	.25	.23	.02	2263.		
1-01	10	50	.01	0.00	.01	0	1-01 25:00	200	.25	.23	.02	2269.		
1-01	15	51	.01	0.00	.01	0	1-01 25:15	201	.25	.23	.02	2275.		
1-01	20	52	.01	0.00	.01	0	1-01 25:30	202	.25	.23	.02	2281.		
1-01	25	53	.01	0.00	.01	0	1-01 25:45	203	.25	.23	.02	2287.		
1-01	30	54	.01	0.00	.01	0	1-01 26:00	204	.25	.23	.02	2293.		
1-01	35	55	.01	0.00	.01	0	1-01 26:15	205	.25	.23	.02	2299.		
1-01	40	56	.01	0.00	.01	0	1-01 26:30	206	.25	.23	.02	2305.		

1.01	4.45	57	.01	.00	.01	12.	1.01	17.15	207	.23	.22	.00	2120.
1.01	4.50	58	.01	.00	.01	13.	1.01	17.20	208	.23	.22	.00	2023.
1.01	4.55	59	.01	.00	.01	14.	1.01	17.25	209	.23	.22	.00	1949.
1.01	5.00	60	.01	.00	.01	15.	1.01	17.30	210	.23	.22	.00	1907.
1.01	5.05	61	.01	.00	.01	16.	1.01	17.35	211	.23	.22	.00	1881.
1.01	5.10	62	.01	.00	.01	17.	1.01	17.40	212	.23	.22	.00	1866.
1.01	5.15	63	.01	.00	.01	18.	1.01	17.45	213	.23	.22	.00	1857.
1.01	5.20	64	.01	.00	.01	19.	1.01	17.50	214	.23	.22	.00	1851.
1.01	5.25	65	.01	.00	.01	20.	1.01	17.55	215	.23	.22	.00	1848.
1.01	5.30	66	.01	.00	.01	21.	1.01	18.00	216	.23	.22	.00	1846.
1.01	5.35	67	.01	.00	.01	22.	1.01	18.05	217	.23	.22	.00	1846.
1.01	5.40	68	.01	.00	.01	23.	1.01	18.10	218	.23	.22	.00	1846.
1.01	5.45	69	.01	.00	.01	24.	1.01	18.15	219	.23	.22	.00	1846.
1.01	5.50	70	.01	.00	.01	25.	1.01	18.20	220	.23	.22	.00	1846.
1.01	5.55	71	.01	.00	.01	26.	1.01	18.25	221	.23	.22	.00	1846.
1.01	5.60	72	.01	.00	.01	27.	1.01	18.30	222	.23	.22	.00	1846.
1.01	5.65	73	.01	.00	.01	28.	1.01	18.35	223	.23	.22	.00	1846.
1.01	5.70	74	.01	.00	.01	29.	1.01	18.40	224	.23	.22	.00	1846.
1.01	5.75	75	.01	.00	.01	30.	1.01	18.45	225	.23	.22	.00	1846.
1.01	5.80	76	.01	.00	.01	31.	1.01	18.50	226	.23	.22	.00	1846.
1.01	5.85	77	.01	.00	.01	32.	1.01	18.55	227	.23	.22	.00	1846.
1.01	5.90	78	.01	.00	.01	33.	1.01	19.00	228	.23	.22	.00	1846.
1.01	5.95	79	.01	.00	.01	34.	1.01	19.05	229	.23	.22	.00	1846.
1.01	6.00	80	.01	.00	.01	35.	1.01	19.10	230	.23	.22	.00	1846.
1.01	6.05	81	.01	.00	.01	36.	1.01	19.15	231	.23	.22	.00	1846.
1.01	6.10	82	.01	.00	.01	37.	1.01	19.20	232	.23	.22	.00	1846.
1.01	6.15	83	.01	.00	.01	38.	1.01	19.25	233	.23	.22	.00	1846.
1.01	6.20	84	.01	.00	.01	39.	1.01	19.30	234	.23	.22	.00	1846.
1.01	6.25	85	.01	.00	.01	40.	1.01	19.35	235	.23	.22	.00	1846.
1.01	6.30	86	.01	.00	.01	41.	1.01	19.40	236	.23	.22	.00	1846.
1.01	6.35	87	.01	.00	.01	42.	1.01	19.45	237	.23	.22	.00	1846.
1.01	6.40	88	.01	.00	.01	43.	1.01	19.50	238	.23	.22	.00	1846.
1.01	6.45	89	.01	.00	.01	44.	1.01	19.55	239	.23	.22	.00	1846.
1.01	6.50	90	.01	.00	.01	45.	1.01	20.00	240	.23	.22	.00	1846.
1.01	6.55	91	.01	.00	.01	46.	1.01	20.05	241	.23	.22	.00	1846.
1.01	6.60	92	.01	.00	.01	47.	1.01	20.10	242	.23	.22	.00	1846.
1.01	6.65	93	.01	.00	.01	48.	1.01	20.15	243	.23	.22	.00	1846.
1.01	6.70	94	.01	.00	.01	49.	1.01	20.20	244	.23	.22	.00	1846.
1.01	6.75	95	.01	.00	.01	50.	1.01	20.25	245	.23	.22	.00	1846.
1.01	6.80	96	.01	.00	.01	51.	1.01	20.30	246	.23	.22	.00	1846.
1.01	6.85	97	.01	.00	.01	52.	1.01	20.35	247	.23	.22	.00	1846.
1.01	6.90	98	.01	.00	.01	53.	1.01	20.40	248	.23	.22	.00	1846.
1.01	6.95	99	.01	.00	.01	54.	1.01	20.45	249	.23	.22	.00	1846.
1.01	7.00	100	.01	.00	.01	55.	1.01	20.50	250	.23	.22	.00	1846.
1.01	7.05	101	.01	.00	.01	56.	1.01	20.55	251	.23	.22	.00	1846.
1.01	7.10	102	.01	.00	.01	57.	1.01	21.00	252	.23	.22	.00	1846.
1.01	7.15	103	.01	.00	.01	58.	1.01	21.05	253	.23	.22	.00	1846.
1.01	7.20	104	.01	.00	.01	59.	1.01	21.10	254	.23	.22	.00	1846.
1.01	7.25	105	.01	.00	.01	60.	1.01	21.15	255	.23	.22	.00	1846.
1.01	7.30	106	.01	.00	.01	61.	1.01	21.20	256	.23	.22	.00	1846.
1.01	7.35	107	.01	.00	.01	62.	1.01	21.25	257	.23	.22	.00	1846.
1.01	7.40	108	.01	.00	.01	63.	1.01	21.30	258	.23	.22	.00	1846.
1.01	7.45	109	.01	.00	.01	64.	1.01	21.35	259	.23	.22	.00	1846.
1.01	7.50	110	.01	.00	.01	65.	1.01	21.40	260	.23	.22	.00	1846.
1.01	7.55	111	.01	.00	.01	66.	1.01	21.45	261	.23	.22	.00	1846.
1.01	7.60	112	.01	.00	.01	67.	1.01	21.50	262	.23	.22	.00	1846.
1.01	7.65	113	.01	.00	.01	68.	1.01	21.55	263	.23	.22	.00	1846.
1.01	7.70	114	.01	.00	.01	69.	1.01	22.00	264	.23	.22	.00	1846.
1.01	7.75	115	.01	.00	.01	70.	1.01	22.05	265	.23	.22	.00	1846.
1.01	7.80	116	.01	.00	.01	71.	1.01	22.10	266	.23	.22	.00	1846.

425.	430.	435.	436.	439.	441.	444.	447.	449.
426.	431.	436.	437.	440.	442.	445.	448.	451.
427.	432.	437.	438.	441.	443.	446.	449.	452.
428.	433.	438.	439.	442.	444.	447.	450.	453.
429.	434.	439.	440.	443.	445.	448.	451.	454.
430.	435.	440.	441.	444.	446.	449.	452.	455.
431.	436.	441.	442.	445.	447.	450.	453.	456.
432.	437.	442.	443.	446.	448.	451.	454.	457.
433.	438.	443.	444.	447.	449.	452.	455.	458.
434.	439.	444.	445.	448.	450.	453.	456.	459.
435.	440.	445.	446.	449.	451.	454.	457.	460.
436.	441.	446.	447.	450.	452.	455.	458.	461.
437.	442.	447.	448.	451.	453.	456.	459.	462.
438.	443.	448.	449.	452.	454.	457.	460.	463.
439.	444.	449.	450.	453.	455.	458.	461.	464.
440.	445.	450.	451.	454.	456.	459.	462.	465.
441.	446.	451.	452.	455.	457.	460.	463.	466.
442.	447.	452.	453.	456.	458.	461.	464.	467.
443.	448.	453.	454.	457.	459.	462.	465.	468.
444.	449.	454.	455.	458.	460.	463.	466.	469.
445.	450.	455.	456.	459.	461.	464.	467.	470.
446.	451.	456.	457.	460.	462.	465.	468.	471.
447.	452.	457.	458.	461.	463.	466.	469.	472.
448.	453.	458.	459.	462.	464.	467.	470.	473.
449.	454.	459.	460.	463.	465.	468.	471.	474.
450.	455.	460.	461.	464.	466.	469.	472.	475.
451.	456.	461.	462.	465.	467.	470.	473.	476.
452.	457.	462.	463.	466.	468.	471.	474.	477.
453.	458.	463.	464.	467.	469.	472.	475.	478.
454.	459.	464.	465.	468.	470.	473.	476.	479.
455.	460.	465.	466.	469.	471.	474.	477.	480.
456.	461.	466.	467.	470.	472.	475.	478.	481.
457.	462.	467.	468.	471.	473.	476.	479.	482.
458.	463.	468.	469.	472.	474.	477.	480.	483.
459.	464.	469.	470.	473.	475.	478.	481.	484.
460.	465.	470.	471.	474.	476.	479.	482.	485.
461.	466.	471.	472.	475.	477.	480.	483.	486.
462.	467.	472.	473.	476.	478.	481.	484.	487.
463.	468.	473.	474.	477.	479.	482.	485.	488.
464.	469.	474.	475.	478.	480.	483.	486.	489.
465.	470.	475.	476.	479.	481.	484.	487.	490.
466.	471.	476.	477.	480.	482.	485.	488.	491.
467.	472.	477.	478.	481.	483.	486.	489.	492.
468.	473.	478.	479.	482.	484.	487.	490.	493.
469.	474.	479.	480.	483.	485.	488.	491.	494.
470.	475.	480.	481.	484.	486.	489.	492.	495.
471.	476.	481.	482.	485.	487.	490.	493.	496.
472.	477.	482.	483.	486.	488.	491.	494.	497.
473.	478.	483.	484.	487.	489.	492.	495.	498.
474.	479.	484.	485.	488.	490.	493.	496.	499.
475.	480.	485.	486.	489.	491.	494.	497.	500.
476.	481.	486.	487.	490.	492.	495.	498.	501.
477.	482.	487.	488.	491.	493.	496.	499.	502.
478.	483.	488.	489.	492.	494.	497.	500.	503.
479.	484.	489.	490.	493.	495.	498.	501.	504.
480.	485.	490.	491.	494.	496.	499.	502.	505.
481.	486.	491.	492.	495.	497.	500.	503.	506.
482.	487.	492.	493.	496.	498.	501.	504.	507.
483.	488.	493.	494.	497.	499.	502.	505.	508.
484.	489.	494.	495.	498.	500.	503.	506.	509.
485.	490.	495.	496.	499.	501.	504.	507.	510.
486.	491.	496.	497.	500.	502.	505.	508.	511.
487.	492.	497.	498.	501.	503.	506.	509.	512.
488.	493.	498.	499.	502.	504.	507.	510.	513.
489.	494.	499.	500.	503.	505.	508.	511.	514.
490.	495.	500.	501.	504.	506.	509.	512.	515.
491.	496.	501.	502.	505.	507.	510.	513.	516.
492.	497.	502.	503.	506.	508.	511.	514.	517.
493.	498.	503.	504.	507.	509.	512.	515.	518.
494.	499.	504.	505.	508.	510.	513.	516.	519.
495.	500.	505.	506.	509.	511.	514.	517.	520.
496.	501.	506.	507.	510.	512.	515.	518.	521.
497.	502.	507.	508.	511.	513.	516.	519.	522.
498.	503.	508.	509.	512.	514.	517.	520.	523.
499.	504.	509.	510.	513.	515.	518.	521.	524.
500.	505.	510.	511.	514.	516.	519.	522.	525.
501.	506.	511.	512.	515.	517.	520.	523.	526.
502.	507.	512.	513.	516.	518.	521.	524.	527.
503.	508.	513.	514.	517.	519.	522.	525.	528.
504.	509.	514.	515.	518.	520.	523.	526.	529.
505.	510.	515.	516.	519.	521.	524.	527.	530.
506.	511.	516.	517.	520.	522.	525.	528.	531.
507.	512.	517.	518.	521.	523.	526.	529.	532.
508.	513.	518.	519.	522.	524.	527.	530.	533.
509.	514.	519.	520.	523.	525.	528.	531.	534.
510.	515.	520.	521.	524.	526.	529.	532.	535.
511.	516.	521.	522.	525.	527.	530.	533.	536.
512.	517.	522.	523.	526.	528.	531.	534.	537.
513.	518.	523.	524.	527.	529.	532.	535.	538.
514.	519.	524.	525.	528.	530.	533.	536.	539.
515.	520.	525.	526.	529.	531.	534.	537.	540.
516.	521.	526.	527.	530.	532.	535.	538.	541.
517.	522.	527.	528.	531.	533.	536.	539.	542.
518.	523.	528.	529.	532.	534.	537.	540.	543.
519.	524.	529.	530.	533.	535.	538.	541.	544.
520.	525.	530.	531.	534.	536.	539.	542.	545.
521.	526.	531.	532.	535.	537.	540.	543.	546.
522.	527.	532.	533.	536.	538.	541.	544.	547.
523.	528.	533.	534.	537.	539.	542.	545.	548.
524.	529.	534.	535.	538.	540.	543.	546.	549.
525.	530.	535.	536.	539.	541.	544.	547.	550.
526.	531.	536.	537.	540.	542.	545.	548.	551.
527.	532.	537.	538.	541.	543.	546.	549.	552.
528.	533.	538.	539.	542.	544.	547.	550.	553.
529.	534.	539.	540.	543.	545.	548.	551.	554.
530.	535.	540.	541.	544.	546.	549.	552.	555.
531.	536.	541.	542.	545.	547.	550.	553.	556.
532.	537.	542.	543.	546.	548.	551.	554.	557.
533.	538.	543.	544.	547.	549.	552.	555.	558.
534.	539.	544.	545.	548.	550.	553.	556.	559.
535.	540.	545.	546.	549.	551.	554.	557.	560.
536.	541.	546.	547.	550.	552.	555.	558.	561.
537.	542.	547.	548.	551.	553.	556.	559.	562.
538.	543.	548.	549.	552.	554.	557.	560.	563.
539.	544.	549.	550.	553.	555.	558.	561.	564.
540.	545.	550.	551.	554.	556.	559.	562.	565.
541.	546.	551.	552.	555.	557.	560.	563.	566.
542.	547.	552.	553.	556.	558.	561.	564.	567.
543.	548.	553.	554.	557.	559.	562.	565.	568.
544.	549.	554.	555.	558.	560.	563.	566.	569.
545.	550.	555.	556.	559.	561.	564.	567.	570.
546.	551.	556.	557.	560.	562.	565.	568.	571.
547.	552.	557.	558.	561.	563.	566.	569.	572.
548.	553.	558.	559.	562.	564.	567.	570.	573.
549.	554.	559.	560.	563.	565.	568.	571.	574.
550.	555.	560.	561.	564.	566.	569.	572.	575.
551.	556.	561.	562.	565.	567.	570.	573.	576.
552.	557.	562.	563.	566.	568.	571.	574.	577.
553.	558.	563.	564.	567.	569.	572.	575.	578.
554.	559.	564.	565.	568.	570.	573.	576.	579.
555.	560.	565.	566.	569.	571.	574.	577.	580.
556.	561.	566.	567.	570.	572.	575.	578.	581.
557.	562.	567.	568.	571.	573.	576.	579.	582.
558.	563.	568.	569.	572.	574.	577.	580.	583.
559.	564.	569.	570.	573.	575.	578.	581.	584.
560.	565.	570.	571.	574.	576.	579.	582.	585.
561.	566.	571.	572.	575.	577.	580.	583.	586.
562.	567.	572.	573.	576.	578.	581.	584.	587.
563.	568.	573.	574.	577.	579.	582.	585.	588.
564.	569.	574.	575.	578.	580.	583.	586.	589.
565.	570.	575.	576.	579.	581.	584.	587.	590.
566.	571.	576.	577.	580.	582.	585.	588.	591.
567.	572.	577.	578.	581.	583.	586.	589.	592.
568.	573.	578.	579.	582.	584.	587.	590.	593.
569.	574.	579.	580.	583.	585.	588.	591.	594.
570.	575.	580.	581.	584.	586.	589.	592.	595.
571.	576.	581.	582.	585.	587.	590.	593.	596.
572.	577.	582.	583.	586.	588.	591.	594.	597.
573.	578.	583.	584.	587.	589.	592.	595.	598.
574.	579.	584.	585.	588.	590.	593.	596.	599.
575.	580.	585.	586.	589.	591.	594.	597.	600.
576.	581.	586.	587.	590.	592.	595.	598.	601.
577.	582.	587.	588.	591.	593.	596.	599.	602.
578.	583.	588.	589.	592.	594.	597.	600.	603.
579.	584.	589.	590.	593.	595.	598.	601.	604.
580.	585.	590.	591.	594.	596.	599.	602.	605.
581.	586.	591.	592.	595.	597.	600.	603.	606.
582.	587.	592.	593.	596.	598.	601.	604.	607.
583.	588.	593.	594.	597.	599.	602.	605.	608.
584.	589.	594.	595.	598.	600.	603.	606.	609.
585.	590.	595.	596.	599.	601.	604.	607.	610.
586.	591.	596.	597.	600.	602.	605.	608.	611.
587.	592.	597.	598.	601.	603.	606.	609.	61

HYDROGRAPH AT SYDNEY FOR FLAP 1, FIG 2

10

THE

SUMMARY OF PMF AND ONE-HALF PMF FLOOD ROUTING

PEAK FLOW AND STORAGE (LONG PERIOD) SUMMARY FOR MULTIPLE PLANTATION ECONOMIC COMPUTATIONS
FLOW IN CUBIC FEET PER SECOND (CUBIC METERS PER SECOND)
AREA IN SQUARE FEET (SQUARE KILOMETERS)

OPERATION	STATION	AREA	PLAY	RATIO	1	RATIO	2	RATIOS APPLIED TO FLUX
					1.00		1.00	
HYDROGRAPH AT	1012	1025	1	1964	10	1965	10	
		2.35		295.2	10	1965	10	
ROUTED TO	1012	1025	1	7020	10	1965	10	
		2.75		212.7	10	1965	10	

SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1 *****									
ELEVATION		INITIAL VALUE		STILLWAY CREST		TOP OF DAM			
STORAGE		417.00		517.00		537.00			
OUTFLOW		72.		72.		669.			
		50%				50%			
RATIO OF PMF		MAXIMUM RESERVOIR W.S. LEV		MAXIMUM STORAGE AC-FT		MAXIMUM OUTFLOW CFS		DURATION OVER TOP HOURS	
1.00		637.00		702.		7620.		.42	
0.50		634.12		702.		1993.		0.00	
								15.00	
								16.25	
								0.00	
								0.00	

PERCENT OF PMF FLOOD ROUTING
EQUAL TO SPILLWAY CAPACITY

PREVIEW OF SEQUENCE OF STREAM NETWORK CALCULATIONS

PUNOFF HYDROGRAPH AT 10212

ROUTE HYDROGRAPH TO 10212

END OF NETWORK

.....
 FLOOD HYDROGRAPH PACKAGE (HEC-1)
 DAN SAFETY VERSION JULY 1972
 LAST MODIFICATION 26 FEB 79

RUN DATE: 79/07/13
 TIME: 13:07:15

DAN SAFETY INSPECTION - MISSOURI
 LOST LINK DAM (13112)
 PERCENT OF DMF DETERMINATION AND ROUTING

JOB SPECIFICATION									
NG	HR	DMF	IDAY	IMR	IMIN	MTRC	IPLT	IPRT	INSTAN
3.0	0	5	0	0	0	0	0	4	0
			JOPEN	MAX	LPADY	TRACE			
			0	0	0	0			

MULTI-PLAN ANALYSIS TO BE PERFORMED
 VOLUME 1 PARTICE 9 LRTIME 1

RTIME: .75 .74 .77 .70 .70 .40 .31 .02 .03

SUB-AREA RULOFF COMPUTATION

INPUT PRECIPITATION INDEX, RATIOS, AND UNIT HYDROGRAPH PARAMETERS

ISTAD	ICOMP	IFCON	ITAGE	UPLT	JUPT	INAME	1STAGE	TAUTO
10112	0	0	2	2	0	1	2	0

HYDROGRAPH DATA									
THYDC	IUNG	TAPCA	CHAP	TRSDA	TRSDC	RATIO	ISHOW	ISAMP	LOCAL
1	2	1.04	0.00	1.00	1.00	0.005	0	0	0

PRECIP DATA						
SPEE	PWC	R6	R24	R48	R72	R96
0.00	24.70	100.00	120.00	130.00	0.00	0.00

LOSS DATA										
LROPT	STARR	DLTR	RTJOL	ERAIN	STWVS	RTJOK	STRTL	CNSTL	ALSHX	RTIMP
0.00	0.00	0.00	1.00	0.00	0.00	1.00	-1.00	-70.00	0.00	0.00

CURVE NO = 78.00 WETNESS = -1.00 EFFECT CH = 78.00

UNIT HYDROGRAPH DATA

RECESSION DATA					
STRTOZ	0.00	GRCSKE	0.00	RTIOP	1.00

END-OF-PERIOD FLOW						
MO,DA	HR,MN	PERIOD	RAIN	EXCS	LOSS	COMP G
0	0	0	0	0	0	0

ROUTE HYDROGRAPH THROUGH LOFT LAKE LHM (10212)

0
2157

-6170

69

131.

of

1

100

TIME

0240 A

5

OUTFLOW

1

•

PEAK OUTFLOW IS 5932, AT TIME 16.00 HOURS

DEAR FLOW AND STORAGE (HEAD OF PERIOD) SUMMARY FOR MULTIPLE PLAN-RATIO ECONOMIC COMPUTATIONS
 FLOW IN 10 FEET DEEP SECOND ECONOMIC METERS PER SECOND
 AREA IN SQUARE MILES (SQUARE KILOMETERS)

OPERATION	STATION	AREA	PLAN	RATIOS APPLIED TO FLOW								
				RATIO 1	RATIO 2	RATIO 3	RATIO 4	RATIO 5	RATIO 6	RATIO 7	RATIO 8	RATIO 9
HYDROGRAPH AT	1:212	1.64	1	7974	8077	8172	8246	8349	8450	8540	8666	8771
	(2475)	(2475)	(2475)	(2475)	(2475)	(2475)	(2475)	(2475)	(2475)	(2475)	(2475)	(2475)
ROUTE TO	1:212	1.64	1	4705	4812	4926	5024	5174	5321	5461	5596	5732
	(2475)	(2475)	(137.24)	(136.43)	(136.43)	(136.43)	(147.27)	(147.52)	(150.72)	(154.64)	(158.47)	(162.33)

SUMMARY OF DAM SAFETY ANALYSIS

PLAN 1

ELEVATION
STORAGE
OUTFLOW

INITIAL VALUE
/17.0
12.0
0.0

SPILLWAY CREST
17.00
1.0
0.0

TOP OF DAM
637.00
66.0
54.75

RATIO OF	MAXIMUM RESERVOIR ELEV	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE HOURS
.75	615.05	452.0	4705.0	0.00	15.00	0.00
.76	616.07	455.0	4815.0	0.00	15.00	0.00
.77	616.73	458.0	4920.0	0.00	15.00	0.00
.78	617.00	461.0	5020.0	0.00	15.00	0.00
.79	617.07	464.0	5174.0	0.00	15.00	0.00
.80	617.93	466.0	5323.0	0.00	15.00	0.00
.81	618.70	468.0	5431.0	0.00	15.00	0.00
.82	619.00	471.0	5596.0	0.00	15.00	0.00
.83	619.00	473.0	5732.0	0.00	15.00	0.00

